# Harrison Township, New Jersey

Preliminary Redevelopment Investigation of Block 52, Lots 8 and 9 March 20, 2014

This page intentionally left blank.

# Acknowledgements

## **MAYOR**

Louis Manzo

## TOWNSHIP COMMITTEE

Louis Manzo, Mayor Dennis Clowney, Deputy Mayor Don Heim Robert Shearer Matt Diggons

# LAND USE BOARD

Joseph Pacera, Chairman
Nancy Kowalik, Vice Chair
Dennis Chambers, Municipal Official
Steve Dickson
John Williams
Kristin Ross
Dennis Bonanni
Lou Manzo, Mayor
Matt Diggons, Councilman
Bill Madara, Alternate No. 1
Paul Mattessich, Alternate No. 2
Paul Donahue, Alternate No. 3
Anthony Difabio, Alternate No. 4

## LAND USE BOARD SECRETARY

Susanne H. Rhudy

# LAND USE BOARD SOLICITOR

Kevin Van Hise, Esquire

## LAND USE BOARD ENGINEER

Hugh Dougherty, PE

## LAND USE BOARD PLANNER

Robert F. Melvin, PP/AICP

prepared by:

Robert F. Melvin, AICP/PP NJ Planner License No. 04018

March 20, 2014

This page intentionally left blank.

# **Table of Contents**

1.0	Introduction	1
1.1.	Study Authorization	1
1.2.	Summary of Findings	1
1.3.	Non Condemnation	1
2.0	Redevelopment Law	2
2.1.	Purpose of the Act	2
2.2.	Redevelopment Procedure	2
3.0	Existing Conditions	3
3.1.	Description of Site Area	3
4.0	Statutory Criteria	6
5.0	Applicability of Statutory Criterion "A"	8
5.1.	Introduction	8
5.2.	Block 52, Lot 8	8
5.3.	Block 52, Lot 9	11

This page intentionally left blank.

# 1.0 Introduction

# 1.1. Study Authorization

Harrison Township through Resolution No. 082-2014 has requested that Group Melvin Design perform a Preliminary Investigation into Block 52, Lots 8 and 9 to ascertain whether this area qualifies under N.J.S.A. 40A:12A-5 as an "Area in Need of Redevelopment"

Map 1 identifies the location and surrounding environs of the Investigation Area

## 1.2. Summary of Findings

The analysis presented within this document serves as the basis for the recommendation that Block 52, Lots 8 and 9 qualify as an Area in Need of Redevelopment.

# 1.2.a. Block 52, Lot 8

This report finds that code violations and issues identified through a property inspection are severe and represent a substantial detriment to the wholesome living of Mullica West Apartment residents. Substantial work must be done to improve ceilings, fix walls, rehabilitate bathrooms and fix kitchens so that they meet basic living standards. In totality the scale of the violations and costs associate with addressing them demonstrate that the Mullica West Apartments are substandard, dilapidated, and obsolescent and meet statutory Criterion A for being designated in Need of Redevelopment.

#### 1.2.b. Block 52, Lot 9

The analysis of Block 52, Lot 9 indicates that the shed, garage, and home have deteriorated significantly and that the owner has, for some time, not undertaken the maintenance to properly address these issues. The result is that all buildings on site meet the statutory criteria for being unsafe and/or dilapidated. In addition, this analysis concludes that the garage and shed are sufficiently outdated in their design and construction as to be considered obsolete for the purposes they are intended to serve.

### 1.3. Non Condemnation

Block 52, Lots 8 and 9 shall be a "Non-Condemnation Redevelopment Area."

As of 2013, the Legislature requires that Preliminary Investigations state whether the redevelopment area determination shall authorize the municipality to use all those powers provided by the Legislature for use in a redevelopment area, including eminent domain. Those Redevelopment Areas where the municipality declares it will not use eminent domain are referred to as "Non-Condemnation Redevelopment Areas."

# 2.0 Redevelopment Law

# 2.1. Purpose of the Act

New Jersey's Local Redevelopment and Housing Law (LRHL), empowers municipalities and local governments with the ability to initiate a process that transforms underutilized or poorly designed properties into healthier, more vibrant, or economically productive land areas. The process has been used successfully across New Jersey to creatively improve properties meeting statutory redevelopment criteria. Projects approved for redevelopment are often eligible for certain types of technical and financial assistance from the State.

# 2.2. Redevelopment Procedure

The LRHL requires municipalities to perform a number of steps before it may exercise its Redevelopment powers. This process is meant, in part, to ensure that the Governing Body acts in concert with the goals and objectives of the Township's Master Plan. Recognizing the Planning Board's role as the steward of the Master Plan, these steps require the Planning Board to make recommendations to the Township Council. The required steps are as follows:

- A. The Governing Body must adopt a resolution directing the Planning Board to perform a preliminary investigation to determine whether a specified area is in need of redevelopment according to criteria set forth in the LRHL (N.J.S.A. 40A:12A-5).
- B. The Planning Board must prepare and make available a map delineating the boundaries of the proposed redevelopment area, specifying the parcels to be included in it. This map should be accompanied by a statement setting forth the basis of the investigation.
- C. The Planning Board must then conduct the investigation and produce a report presenting the findings. The Board must also hold a duly noticed hearing to present the results of the investigation and to allow interested parties to give testimony. The Planning Board then may adopt a resolution recommending a course of action to the Governing Body.
- D. The Governing Body may act on this recommendation by adopting a resolution designating the area an "Area in Need of Redevelopment". The Governing Body must make the final determination as to the Redevelopment Area boundaries.
- E. A Redevelopment Plan must be prepared establishing the goals, objectives, and specific actions to be taken with regard to the "Area in Need of Redevelopment."
- F. The Governing Body may then act on the Plan by passing an ordinance adopting the Plan as an amendment to the Township's Zoning Ordinance.

Only after completion of this process is the Township able to exercise the powers granted to it under the State Redevelopment Statute.

# 3.0 Existing Conditions

# 3.1. Description of Site Area

Block 52, Lot 8, also known as "Mullica West Apartments" is located in Harrison Township off of High Street as illustrated on Figure 1. In Tax year 2013, Block 52 Lots 8.01, 8.02, and 11.01 were consolidated with Lot 8 for tax purposes. Appendix B - Lot Consolidation provides documentation from the Tax Assessor.

Mullica West Apartments is currently an affordable housing complex for families located in Harrison Township, Gloucester County. Mullica West Apartments was developed over 30 years ago through the USDA Section 515 Program, and consists of 7 buildings and 168 apartment units with one unit utilized for management and leasing. USDA has determined that this project is eligible to leave its program and can be converted to market rate housing.


The property owner has obtained a professionally prepared capital needs assessment to establish the scope of rehabilitation which will upgrade all apartments to meet construction code requirements, achieve energy star standards for the project, replace all central heat and air conditioning units, replace flooring, and renovate all kitchens and baths. (Appendix C, Appendix D, and Appendix E)

According to the property owner, USDA will provide rental assistance to this project on a year to year basis. However, the property owner has also stated that this rental assistance is in jeopardy and subject to loss without the efforts outline in the capital needs assessment.

Figure 2 identifies the location of the various buildings and improvements on the Mullica West Apartments site.

Block 52, Lot 9 is located behind Lot 8 and fronts onto New Jersey 45. It measures approximately 5.2 acres. There are currently three structures located on site: a single-family house, a garage, and small utility shed.

Figure 1. Aerial of Site



SMCSOVER CERVER AND AND ADDRESS CONTRACTOR  $\triangleleft \triangleleft$ 

Figure 2. Mullica West Site Configuration

# 4.0 Statutory Criteria

A study area qualifies as being an "Area in Need of Redevelopment" if it meets at least one of the eight statutory criteria listed in Section 40A:12A-5 of the Local Redevelopment and Housing Law:

- A. The generality of buildings are substandard, unsafe, unsanitary, dilapidated, or obsolescent, or poses any of such characteristics, or are so lacking in light, air, or space, as to be conducive to unwholesome living or working conditions.
- B. The discontinuance of the use of buildings previously used for commercial, manufacturing, or industrial purposes; the abandonment of such buildings; or the same being allowed to fall into so great a state of disrepair as to be untenable.
- C. Land that is owned by the municipality, the county, a local housing authority, redevelopment agency or redevelopment entity, or unimproved vacant land that has remained so for a period of ten years prior to adoption of the resolution, and that by reason of its location, remoteness, lack of means of access to developed sections or portions of the municipality, or topography, or nature of the soil, is not likely to be developed through the instrumentality of private capital.
- D. Areas with buildings or improvements which, by reason of dilapidation, obsolescence, overcrowding, faulty arrangement or design, lack of ventilation, light and sanitary facilities, excessive land coverage, deleterious land use or obsolete layout, or any combination of these or other factors, are detrimental to the safety, health, morals, or welfare of the community.
- E. A growing lack or total lack of proper utilization of areas caused by the condition of the title, diverse ownership of the real properties therein or other similar conditions which impede land assemblage or discourage the undertaking of improvements, resulting in a stagnant and unproductive condition of land potentially useful and valuable for contributing to and serving the public health, safety and welfare, which condition is presumed to be having a negative social or economic impact or otherwise being detrimental to the safety, health, morals, or welfare of the surrounding area or the community in general.
- F. Areas, in excess of five contiguous acres, whereon buildings or improvements have been destroyed, consumed by fire, demolished or altered by the action of storm, fire, cyclone, tornado, earthquake or other casualty in such a way that the aggregate assessed value of the area has been materially depreciated.
- G. In any municipality in which an enterprise zone has been designated pursuant to the "New Jersey Urban Enterprise Zones Act," P.L.1983, c.303 (C.52:27H-60 et seq.) the execution of the actions prescribed in that act for the adoption by the municipality and approval by the New Jersey Urban Enterprise Zone Authority of the zone development plan for the area of the enterprise zone shall be considered sufficient for the determination that the area is in need of redevelopment pursuant to sections 5 and 6 of P.L.1992, c.79 (C.40A:12A-5 and 40A:12A-6) for the purpose of granting tax exemptions within the enterprise zone district pursuant to the provisions of P.L.1991, c.431 (C.40A:20-1 et seq.) or the adoption of a tax abatement and exemption ordinance pursuant to the provisions of P.L.1991, c.441 (C.40A:21-1 et seq.). The municipality shall not utilize any other redevelopment powers

within the urban enterprise zone unless the municipal governing body and planning board have also taken the actions and fulfilled the requirements prescribed in P.L.1992, c.79 (C.40A:12A-1 et al.) for determining that the area is in need of redevelopment or an area in need of rehabilitation and the municipal governing body has adopted a redevelopment plan ordinance including the area of the enterprise zone.

H. The designation of the delineated area is consistent with smart growth planning principles adopted pursuant to law or regulation.

N.J.S.A. 40A:12A-3 further states that "A redevelopment area may include lands, buildings, or improvements which of themselves are not detrimental to the public health, safety or welfare, but the inclusion of which is found necessary, with or without change in their condition, for the effective development of the area of which they are a part." This is commonly referred to as the "Section 3 Criteria."

According to the Redevelopment Handbook, this section allows for the inclusion of properties that do not meet the statutory criteria but are," essential to be included in the designation to effectively redevelop the area." Examples of such properties include properties located within and surrounded by otherwise blighted area, property that are needed to provide access to an area to be redeveloped, areas needed for infrastructure or utilities, or properties that otherwise could be determined to be critical to the area's successful redevelopment.

# 5.0 Applicability of Statutory Criterion "A"

#### 5.1. Introduction

## 5.1.a. Statutory Language

The generality of buildings are substandard, unsafe, unsanitary, dilapidated, or obsolescent, or poses any of such characteristics, or are so lacking in light, air, or space, as to be conducive to unwholesome living or working conditions.

#### 5.1.b. Conclusions

Based on information obtained through a property owner inspection, NJ Department of Community Affairs report, and a capital needs assessment financial statement Group Melvin Design concludes that substantial work must be done to Lot 52, Block 8 ("Mullica West Apartments") to improve ceilings, fix walls, rehabilitate bathrooms and fix kitchens so that they meet basic living standards. These issues have persisted from 2010 through 2012 and were almost certainly present before the 2010 property inspection. The deterioration of the units has not been meet with sufficient maintenance, resulting in a continued threat to the wholesome living conditions of occupants. In totality the violations and issues identified in the following analysis demonstrate that the Mullica West Apartments are substandard, dilapidated, and obsolete and thus meet statutory Criterion A for being designated in Need of Redevelopment.

The analysis of Block 52, Lot 9 indicates that the shed, garage, and home have deteriorated significantly and that the owner has, for some time, not undertaken the maintenance to properly address these issues. The result is that all buildings on site meet the statutory criteria for being unsafe and/or dilapidated. In addition, this analysis concludes that the garage and shed are sufficiently outdated in their design and construction as to be considered obsolete for the purposes they are intended to serve.

### 5.2. Block 52, Lot 8

As part of their efforts to convert Mullica West to market rate units, the property owner has obtained a professionally prepared capital needs assessment to establish the scope of rehabilitation which will upgrade all apartments to meet construction code requirements. That assessment included:

- a 2010 Property Owner Inspection (Appendix C);
- a 2012 NJ Department of Community Affairs violations report (Appendix D); and
- an estimate of the cost necessary to address issues identified in those reports (Appendix E).

The following analysis is based on those documents and interviews with the property owner.

#### 5.2.a. Property Owner Inspection

As part of the capital needs assessment, the property owner provided a 2010 unit inspection report. That report identified a variety of improvements that must be made to the various buildings and units. Although they are too numerous to detail in full here, the following is a list of the types of

improvements that are most likely to impact the health and safety of residents (for a complete list of all improvements see Appendix C - Property Owner Inspection)

#### Kitchens:

- · Kitchen faucet replacements
- Sink replacements
- · Fix leaky and clogged drains
- Ventilation fan replacements

#### Bathrooms

- Caulking of tubs
- · Resurfacing of bathroom tubs
- New faucet systems
- New exhaust fans

#### Other areas within units

- Fire detector replacements
- Windows and window treatments replacements
- Door replacements
- · Replacement of handrails
- · Ceiling fixes
- New hot water heaters
- Fixing of holes in walls and damage to drywall

What is clear from this report is that in 2010, the property was in need of substantial repairs in order to meet basic living standards. Faulty fire detectors, broken hot water heaters, poorly draining sinks, dilapidated/un-repaired ceilings and walls are all signs that many units were in a state of substantial disrepair and constituted a detriment to the to wholesome living conditions of the people who occupy them.

#### 5.2.b. DCA Violations

On August 8, 2012, the New Jersey Department of Community Affairs inspected the Mullica West apartments. In a report submitted by the property owner, the DCA identified more than 120 violations across all the units (Appendix D). At the time of that report, only half of those violations had been addressed.

The number of violations is too numerous to provide a complete list in the body of this report. Nonetheless, the DCA violation follow the same pattern identified by the property owner when doing their 2010 annual unit inspections: faulty bathroom amenities, broken kitchen appliances, and issues with the general condition of many units. In addition, the DCA identified safety issues associated with hot water heaters and sidewalks, among others.

### 5.2.c. Cost of Improvements

As part of its Capital Needs Assessment, the property owner has identified the cost of bringing the building up to code. These costs are identified in worksheets provided in Appendix E.

According to the property owner, more than \$10 million dollars of repairs and improvements are need to the building and site. Group Melvin Design is confident that the majority of this work is needed to ensure the property meets basic living standards. These improvements are not luxury items. Instead they are basic improvements for a renovations that, according to the current property owner, will still target those below 60% of county median income adjusted for family size, assuming USDA rental assistance.

The following upgrades are particularly noteworthy. The cost of the improvements have been included to indicate the scale of the problems which must be addressed.

- New top coat of parking and re-striping (\$150,000): well regulated parking is a requirement
  in all suburban housing developments. The fact that the municipality requires parking only
  underlines the clear need of residents to have a safe and secure place to house their primary
  means of accessing services and employment.
- Site Lighting (\$562,500): Lighting is an essential safety element. Improper lighting makes hazards harder to avoid and has been shown to increase incidences of both property and violent crime.
- Plumbing and Sanitary system clean out (\$17,000): A well functioning sanitary system is a basic human need. So much so that the US Census has historically used lack of access to plumbing facilities as a major indicator of poverty.
- Roof Replacement (\$317,100): the capital needs assessment has identified new roofs for 7 buildings. Roofs can be fire hazards if they allow water to get into areas where there is electrical equipment. In addition, poor roofing can increase the amount of mold and mildew that builds up in a unit which can have serious health effects for residents. If such issues remain untreated, framework can weaken, making the entire structure unsafe to inhabit.
- Windows (\$108,500): Broken, malfunctioning and missing windows can be create unwholesome
  living conditions for residents. The need to assess light and air is the foundation of many of the
  building and zoning codes that currently regulate our built environment. Without access to
  fresh air, people can develop respiratory illnesses and diseases have a higher likelihood of
  spreading amongst residents.
- Hard-wired Smoke Detectors (\$126,000): Well functioning smoke detectors are one of the
  best and most important safety elements in any home. Hard wired smoke detectors are very
  important in multi-family housing buildings. In general, they have a signal wire connected
  between multiple detectors that allows them to communicate to each other when there is
  smoke. This means that if there is a fire in one unit, smoke detector in adjacent units will go off.
  This gives all residents sufficient time to evacuate in case of fire.
- Hot water heaters (\$285,600): The average life of a residential water heater is 10 years and failing hot water heaters prose a threat to occupants and the buildings they inhabit. Poorly maintained or failing heaters can explode, spray hot water from a ruptured tank and dissolve

the drywall around it. In less catastrophic ways, they can also begin to leak. Leaking heaters can cause mold and mildew, which is a detriment to human health while ruining flooring and drywall.

The above listed elements are only some of the many improvements necessary to ensure the building meets standards while addressing dilapidation and obsolete conditions. The magnitude of these costs indicate that such improvement are not minor, but will involve substantial work.

#### 5.2.d. Conclusions

The character of the violations identified by DCA, the list of capital improvements identified by the property owner, and a detailed analysis of photographs taken of the units and the building indicates that substantial work must be done to improve ceilings, fix walls, rehabilitate bathrooms and fix kitchens so that they meet basic living standards. The fact that these issues persisted from 2010 through 2012 indicates that neglect will likely continue to pose a treat to the wholesome living conditions of occupants. In totality these violations demonstrate that the Mullica West Apartments are substandard, dilapidated, and obsolescent and thus meet statutory Criterion A for being designated in Need of Redevelopment.

# 5.3. Block 52, Lot 9

In a correspondence dated March 20, 2014, the contract purchaser, Ron Rukenstein, detailed a number of issues related with the buildings on Lot 9. That correspondence can be found in Appendix F - Rukenstein Correspondence.

#### 5.3.a. Shed and Garage

According to that report, there exists both a shed and garage that are clearly in disrepair and have outlived their useful life. These structures are of insufficient size for today's standards and based on condition and obsolescence would be best suited for demolition.

Based on images provided in that report (Figure 3), it is clear to see that the shed has substantial structural damage, with the roof bowing in at the top. In addition, the roof has signs of heavy molding. The structure has clearly not been maintained for years and is unsafe to use for its intended purpose.

Pictures of the garage show a similar condition. The roof shows significant signs of rust and lack of maintenance. The gutters are clearly falling off of the structure and the rust indicate the building is not waterproof. As a result, the garage is likely to have serious mold and water issues that could impact the structural integrity of the building. These clearly demonstrate that the building is substandard and dilapidated.

Additionally, the garage does not have doors. Any modern garage would have some means of preventing unauthorized users from accessing the structure. Combined with the rusted roofing and possible structural issues, it is clear that the garage should be considered obsolete for the purposes it was intended to serve.

## 5.3.b. On-Site House

Mr. Rukenstein's report also notes that the single family home on the property maintains substandard and unsanitary conditions. There are several areas where water leaks remain evident on the ceilings. Furthermore the foundation and mortar joints are in disrepair. Leaks in the ceiling indicate that

the roof may be compromised. This water damage is likely to have produced mold and possibly structural damage to the building. In either case, the structure is likely to be an unhealthy living condition for the resident.

It should also be noted that leaking water can be a fire hazard if the problem allows water to get into areas where there is electrical equipment. The image provided by Mr. Rukenstein shows a room that is cluttered with highly combustible materials. The house is wood framed. Combined this evidence indicates that there may be a substantial fire risk which poses a serious treat to the health and safety of both the resident and neighbors.

#### 5.3.c. Conclusions

The above analysis indicates that the shed, garage, and home have deteriorated significantly and that the owner has, for some time, not undertaken the maintenance to properly address these issues. The result is that all buildings on site meet the statutory criteria for being unsafe and/or dilapidated. In addition, this analysis concludes that the garage and shed are sufficiently outdated in their design and construction as to be considered obsolete for the purposes they are intended to serve.

Figure 3. Images of Block 52, Lot 9







Top left: Shed Top Right: Garage Left: House



# RESOLUTION NO. 082-2014

RESOLUTION OF THE MAYOR AND COMMITTEE OF THE TOWNSHIP OF HARRISON AUTHORIZING THE JOINT LAND USE BOARD TO CONDUCT A PRELIMINARY INVESTIGATION TO DETERMINE WHETHER LOTS 8 AND 9 IN BLOCK 52 ON THE OFFICIAL TAX MAP OF THE TOWNSHIP OF HARRISON QUALIFY AS AN AREA IN NEED OF REDEVELOPMENT

WHEREAS, the Local Redevelopment and Housing Law, N.J.S.A. 40A:12A-1, et seq., provides a mechanism to empower and assist local governments in efforts to promote programs of redevelopment; and

WHEREAS, the Local Redevelopment and Housing Law sets forth a specific procedure for establishing an area in need of redevelopment; and

WHEREAS, N.J.S.A. 40A:12A-6 authorizes the governing body of the municipality by Resolution, to cause its Planning Board to conduct a preliminary investigation to determine whether the proposed area is an area in need of redevelopment according to the criteria set forth in N.J.S.A. 40A:12A-5; and

WHEREAS, the proposed Redevelopment Area (Block 52, Lots 8 and 9) determination shall authorize the municipality to use all those powers provided by the Legislature for use in a Redevelopment Area, other than the use of eminent domain; and, as such, the Redevelopment Area shall be established and be referred to as a "Non-Condemnation Redevelopment Area"; and

WHEREAS, the Township Committee of the Township of Harrison, Gloucester County, has determined that an investigation and inquiry should be made to see if said area is in need of redevelopment pursuant to the aforementioned State Statute; and

WHEREAS, the Township of Harrison governing body wishes to direct the Joint Land Use Board to undertake a preliminary investigation to determine whether the following properties identified as and consisting of Blocks 52, Lots 8 and 9 qualify as an area in need of redevelopment pursuant to N.J.S.A. 40A:12A-5; and

WHEREAS, the Township Committee considers it to be in the best interest of the Township to directs its Joint Land Use Board to conduct such an investigation regarding said area/property.

NOW, THEREFORE, BE IT RESOLVED by the Mayor and Committee of the Township of Harrison, County of Gloucester and State of New Jersey as follows:

- 1. The Joint Land Use Board of the Township of Harrison is hereby directed to undertake a preliminary investigation to determine whether Block 52, Lots 8 and 9 is a "Non-Condemnation Redevelopment Area such that the municipality may use all those powers provided by the Legislature for use in a Redevelopment Area", other than the use of eminent domain, according to the criteria set forth in N.J.S.A. 40A:12A-1, et seq.; and
- 2. The staff of the Joint Land Use Board and its consultants are hereby directed to assist the Joint Land Use Board in conducting the area in need of redevelopment investigation; and
- 3. The Township Clerk shall forward a copy of this Resolution to the Chairman and Secretary of the Joint Land Use Board for immediate action; and
- 4. The preliminary investigation, once completed, shall be submitted to the Township Committee for review and approval in accordance with the provisions of the Redevelopment and Housing Law, N.J.S.A. 40A:12A-1, et seq.

ADOPTED at a regular meeting of the Mayor and Township Committee of the Township of Harrison, County of Gloucester, State of New Jersey held on March 5, 2014.

TOWNSHIP OF HARRISON

OUTS F. MANZO, MAYO

DIANE L. MALLOY Municipal Clerk

Į	<u> </u>				
l	R	OLL CALI	_ VOTE		
l	COMMITTEE MEMBER	AYES	NAYS	ABSTAIN	ABSENT
I	Manzo	V			
	Clowney	1			
ĺ	Diggons				
I	Heim				1
i	Shearer				

# CERTIFICATION

I hereby certify that the above resolution is a true copy of a resolution adopted by the Township Committee of the Township of Harrison, County of Gloucester, State of New Jersey, at a meeting held by he same on March 5, 2014 in the Harrison Township Municipal Building, 114 Bridgeton Pike, Mullica Hill, New Jersey 08062.

DIANE L. MALLOY

Municipal Clerk



# GLOUCESTER COUNTY OFFICE OF ASSESSMENT



FREEHOLDER DIRECTOR
Robert M. Damminger

June 12, 2103



Ron Rukenstein, PP, AICP Rukenstein & Associates, LLC PO Box #1 Titusville, NJ 08560

RE: Block 52, Lot 8 Mullica West LTD

58 Woodstown Rd, Harrison Twp, NJ

COUNTY ASSESSOR Robyn Glocker-Hammond

Dear Mr. Rukenstein,

I understand that you are applying for a tax credit and trying to obtain proof from the Assessor's Office that Lots 8.01, 8.02 and 11.01 were consolidated with Lot 8 for tax year 2013.

Clayton Complex, Bldg. A 1200 N. Delsea Drive Clayton, NJ 08312 Please allow this letter to confirm that Lots 8.01, 8.02 and 11.01 were removed from the tax list and that only Lot 8 is receiving a 2013 tax bill. Additionally, I have enclosed a copy of the updated tax map reflecting the consolidation.

Phone 856-307-6445 Fax 856-307-6447 Should you require any further assistance, please don't hesitate to contact my office.

Sincerely,

www.gloucestercountyni.gov

Robyn Glocker-Hammond, County Assessor Gloucester County Office of Assessment

New Jersey Relay Service-711 Gloucester County Relay Service (TTY/TTD)- (856)848-6616 Enclosure (Tax Map)
Cc: J. Timothy Kernan, PD, PP, CME

/rlh

# COMMUNICATIONS WITH NIRRINGN TWP CONFIRMING LUT Ron Rukenstein CONDLIGOTION.

From:

Tim Kernan <tkernan@kernaneng.com>

Sent:

Tuesday, June 11, 2013 8:07 AM

To:

Ron Rukenstein

Cc:

jbibeau@tcpcontrol.com; Jack Plackter; Scohen45@aol.com; Michelle Young

Subject:

Fwd: Mullica West Lot Consolidation

Attachments:

GC TAX ASSESSOR CONSOLIDATION OF LOTS.pdf; ATT00001.htm

See below and attached

Sent from my iPhone

Begin forwarded message:

From: "Susanne Rhudy" < srhudy@harrisontwp.us>

Date: June 11, 2013, 8:04:47 AM EDT

To: "'Tim Kernan'" < <a href="mailto:tkernan@kernaneng.com">tkernan@kernaneng.com</a>>
Subject: RE: Mullica West Lot Consolidation

Tim,

The lot consolidation was done unbeknownst to the township. I noticed it on our tax maps.

Attached is a document UCB's attorney got from the tax assessor. It does not show the date of consolidation.

Susanne H. Rhudy
Land Use Administrator/Joint Land Use Board Secretary
Municipal Housing Liaison
Township of Harrison
114 Bridgeton Pike
Mullica Hill, NJ 08062
(856)478-6522
(856)478-6287 fax
srhudy@harrisontwp.us

From: Tim Kernan [mailto:tkernan@kernaneng.com]

Sent: Monday, June 10, 2013 9:23 PM

To: Susanne Rhudy

Subject: Fwd: Mullica West Lot Consolidation

Hi is there anything you could gather from the tax office in this regard? Any help would be appreciated.

Thanks, Tim

Sent from my iPad

Begin forwarded message:



# STEVEN • S • COHEN • ARCHITECT • P.C. •

Capital Needs Assessment Mullica West Apartments, Mullica Hill, NJ Performed by Steven S. Cohen Architects

11. Annual Inspection Reports performed by Mullica West Apartments

# MULLICA WEST 2010 Annual Unit Inspection

UNIT:#	REPAIR DESCRIPTION	W::0:#	COMPLETION DATE
102	Kitchen: Replace drip pans	3368-1	
	Repair drawer face	3369-1	
	Bathrm: Caulk tub	3369-2	
104	Kitchen: Replace drip pans	3533-1	
107	Living Area: Replace carpet-original	2276-2	
109	Kitchen: Replace drip pans Bathrm: Caulk	3371-1	
	Saaanii Gayak	3371-2	
110	Bathrm: Replace pump fill valve	3372-1	

UNIT#	REPAIRS DESCRIPTION	W:0.#	COMPLETION DATE
111	Kitchen: Replace drip pans Glue molding along wall	3373-1 3373-2	
112	Kitchen: Replace drip pans Bathroom: Caulk tub Check noise in exhaust fan	3374-1 3375-1 3375-2	

113	Kitchen: Repair sink drip	3376-1
114	Bathrm: Tub faucet leak	3378-1
115	Kitchen: Replace faucet handle Replace refrigerator crisper	3379-1 3379-2
116	Kitchen: Replace faucet Replace drip pans	3380-1 3380-2
UNIT #	REPAIRS DESCRIPTION	W.O. # GOMPLETION DATE
117	Kitchen: Replace faucet	3385-1
120	Bathrm: Caulk tub Check noise in exhaust fan LygRm: Adjust bi-fold doors	3408-1 3409-1
122	Kitchen: Faucet leaks Replace refrigerator crisper Bathrm: Replace sink	3411-1 3411-2 3411-3
123	Kitchen: Replace faucet Bathrm: Resurface tub Bedrm #2: Bi-fold door off track	3412-3
124	Bathrm: Resurface and caulk tub	3413-1

# MULLICA WEST 2010 Annual Unit Inspection

UNIT #	REPAIR DESCRIPTION	W. O. #	COMPLETION DATE
201	Kitchen: Replace drip pans	3534-1	
203	Kitchen: Replace faucet stem	3386-1	
204	Kitchen: Replace drip pans Bathrm: Check toilet tank	3535-1 3387-1	
205	Kitchen: Faucet leaks	3388-1	
206	Kitchen: Faucet leaks	3392-1	

unit #	REPAIRS DESCRIPTION	<b>W</b> .O.#	COMPLETION: DATE
209	Bedrm #1: Replace closed light fixture Replace window treatment	3393-1 3391-1	
211	Bathroom: Caulk tub Bedrm: Replace window treatment Lvg Area: Replace detector Replace handrail bracket and patch hole	3394-1 3395-1 3396-1 3397-1	
212	Lvg Area: Replace battery	3398-1	

213	Kitchen: Replace drip pans Replace crisper and shelf bar	3400-1 3399-1	
214	Bathrm: Resurface and caulk tub Bedrm #1: Bi-fold door off track Entrance Dr: Replace door bell	3401-1 3107-1 3402-1	
218	Kitchen: Replace crisper Repair drawer face Bathrm: Resurface tub	3404-1 3405-1 3406-1	
UNIE #	REPAIRS DESCRIPTION	W.O. #2	COMPLETION: DATE
219	Kitchen: Faucet leaks	3407-1	
		J407-1	

# MULLICA WEST 2010 Annual Unit Inspection 300 Building

Date: August 5, 2009 Updated: 2/8/08

UNIT #	REPAIR DESCRIPTION	W. O. #	COMPLETION DATE
301	Kitchen: Replace drip pans Bathrm: Caulk tub Lvg Rm: Adj. Bifold door	3602-1 2369-1 3603-1	DAIL
302	Bathrm: Resurface tub Bedroom #1: Replace window treatments	3604-1 3605-1	
304	Kitchen: Replace handle on refrigerator Closet Dr: Repair door and paint trim	3607-1 3608-1	
305	Shed Door: Replace brick molding	3609-1	
307	Hallway: Adjust Bi-fold Door Breaker Box: Add spacer	3610-1 3611-1	

UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION DATE
308	Kitchen: Replace drip pans Sink faucet leaks Bathrm: Tub-caulk Living Rm: Replace window treatments Bedroom: Replace window treatments	3599-1 3601-1 3612-1 3598-1 3598-1	

309	Living Rm: Adjust Bi-fold doors	3613-1	
	Taylor Dr. Tota abbit	<b>5</b> 415 .	
1			
310	Bathroom: Replace sink	3614-1	-
1			
	Kitchen: Replace crisper	3615-1	
314	Bathroom: Caulk tub	3617-1	
314	Bedroom # 1: Replace closet door handle	3618-1	
	Bedroom # 2: Replace screen	3620-1	
	Dedition # 2. Replace screen		
215	Deduce one Coult to	3621-1	
315	Bathroom: Caulk tub		
316			
11		~	
	Bathrm: caulk tub	2405-1	
- 10	Bathrm: caulk tub	2405-1	
UNIT #	Bathrm: caulk tub  REPAIRS DESCRIPTION	2405-1 W.O. #	COMPLETION
			COMPLETION
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION
			COMPLETION
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION
UNIT #	REPAIRS DESCRIPTION  H/W/H: Replace	W.O. #	COMPLETION
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION
UNIT #	REPAIRS DESCRIPTION  H/W/H: Replace	W.O. # 2385-2 2386-1	COMPLETION
UNIT # 318	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter	W.O. # 2385-2 2386-1 2387-2	COMPLETION
UNIT #	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter  Bathrm: Caulk tub	W.O. # 2385-2 2386-1	COMPLETION
UNIT # 318	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter	W.O. # 2385-2 2386-1 2387-2	COMPLETION
UNIT # 318	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter  Bathrm: Caulk tub	W.O. # 2385-2 2386-1 2387-2	COMPLETION
UNIT # 318	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter  Bathrm: Caulk tub	W.O. # 2385-2 2386-1 2387-2	COMPLETION
UNIT # 318	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter  Bathrm: Caulk tub	2385-2 2386-1 2387-2 2387-1	COMPLETION
318 319 320	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter  Bathrm: Caulk tub Spackle and paint ceiling	2385-2 2386-1 2387-2 2387-1	COMPLETION
UNIT # 318	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter  Bathrm: Caulk tub Spackle and paint ceiling  Bathroom: Caulk tub	2385-2 2386-1 2387-2 2387-1	COMPLETION
318 319 320	REPAIRS DESCRIPTION  H/W/H: Replace  Kitchen: Exhaust fan hitting filter  Bathrm: Caulk tub Spackle and paint ceiling	2385-2 2386-1 2387-2 2387-1	COMPLETION

322	Kitchen: Replace exhaust fan filter Bathrm: Caulk tub	3622-1 2389-3	
323	Bathroom: Caulk & Resurface	2390-2 2409-2	

# MULLICA WEST 2010 Annual Unit Inspection

UNIT #	REPAIR DESCRIPTION	W. O. #	COMPLETION DATE
324	Kitchen: Replace front right burner Lvg Rm: Adjust bi-fold door	3623-1	
302	Bathrm: Caulk tub Lvg Rm: Closet ceiling bowed	2370-1	
303	Hall Closet: Replace H/W heater	2371-1	
304	Bathrm: Replace faucet stem	2372-1	
305	Hallway: Replace compression fitting on H/W heater	2379-1	

UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION DATE
306	Kitchen: Replace floor  Drain leaks	2374-1 2374-2	
	Bathrm: Sink drain runs slow Tub-caulk	2374-3 2374-4	

307	Kitchen: Repair top drawer next to refrigerator Breaker Box: Needs 1 spacer H/W Heater: Replace	2376-1 2376-2 2376-3	
308	H/W Heater: Replace, leaking	2378-1	
309	Kitchen: faucet leaks Bathrm: replace sink caulk tub Lvg RM: adjust bi-fold doors Breaker Box: install spacer Bedrm: cluttered	2377-1 2377-2 2377-3 2377-4 2377-5 2377-6	
310	Kitchen: re-tile floor Bathrm: replace sink Entrance: re-attach chain	2378-1 2378-2 2378-3	
311	Bathrm: replace sink caulk tub Bedrins: holes in screen replace screen	2379-1 2379-2 2379-3	
UNIT #	REPAIRS DESCRIPTION	W.O. #	COMPLETION DATE
312	Bathrm: caulk tub Lvgrm: replace closet door knob Entrance: repair storm door screen	2380-1 2380-2 2380-3	
313	Kitchen: Replace Faucet repair sink drawer face Bathrm: ceiling water stains replace sink replace exhaust fan Closets: cluttered Cluttered	2381-1 2381-2 2381-3 2381-4 2381-5 2381-6 2381-7	

314	Kitchen: replace faucet stem replace cabinet door Bathrm: caulk tub Lvgrm: closet door removed Bedrm 1: replace closet knob replace shades Bedrm 2: replace closet door pin replace shades	2382-1 2382-2 2382-3 2382-4 2382-5 2382-6 2382-7 2382-8	
315	Breaker Box: needs spacer	2383-1	
316	Kitchen: replace faucet Bathrm: caulk tub tub drain backs up Shed: gas can	2404-1 2406-1 2407-1 2408-1	completed
318	Kitchen: replace light switch H/W Heater: replace	2386-1	

## 2010 Annual Unit Inspection Report - MULLICA WEST

### Date AUI Completed:12/1/2010

Γ		T	T	7	T	Τ	T	T	Τ	T	Τ	Τ	Τ	Τ	Τ	Τ	Τ	Τ	Τ	Τ		Τ	Τ	Τ	Γ	1		Τ	Τ	Τ		Τ	Γ	<u> </u>
W.O.#		4104-1	4105-1	4106-1	4107-1	4108-1	4109-1	4110-1	4111-1	4112-1	4113-1	4114-1	4115-1	4116-1	4117-1	4118-1	4119-1	4120-1	4121-1	4122-1	4123-1	4124-1	4125-1	4126-1	4127-1	4128-1	4129-1	4130-1	4131-1	4132-1	4133-1	4134-1	4135-1	4136-1
Completion Date																		- Control Control																
Target Completion Date	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11	Mar-11
Comments	501 Replace drip pans	502 Replace BR threshold	502 Replace BR sink	503 Inspect kitchen sink drain	504 Replace drip pans	504 Low water pressure	504 Toilef runs	504 Hot water heater closet blocked	505 Replace drip pans	506 Replace rusted BR sink	506 Caulk tub	506 BR light cover fell off	506 Replace window treatments in both Bedrm/Livrm	506 Adjust bi-fold in livrm	506 Hallway light cover fell off	506 Exterior light globe missing	509 Replace drip pans	509 Ceiling pealing/leaking	509 Sink leaking	9 Repair light switch	509 Replace blinds in both Bedrm/Livrm	511 Replace blinds in all three rooms bedrm #1 & #2, livrm	1 Window in bedrm #1 leaks water	511 Replace drip pans	512 Caulk tub	512 Adjust bi-fold in bedrm #2	513 Replace drip pans	513 Bathroom ceiling paint chipping	513 Adjust closet door in livrm	514 Repair kitchen floor tile	514 Replace drip pans	4 Range burner not working	4 Repair bathroom floor tile	4 Replace rusted BR sink
Apt.																							51	51	5	51	51	51	51	51	51	514	514	514
Bldg #	200	200	200	200	200	200	200	500	200	200	200	500	200	200	500	500	200	200	200	200	900	200	200	200	500	500	200	500	500	200	500	200	200	200

)

500	514 Adiust bedrn #4 closet door		
200	514 Remove soffit bottom of stone	Mar-11	4137-1
500	515i Replace drip pans	Mar-11	4138-1
200	515 Replace fivrm blinds	Mar-11	4139-1
200	515 Adjust half coset door	War-11	4140-1
500	516 Caulk tub	Mar-11	4141-1
500	516 Adjust livrm closet door	Mar-11	4142-1
200	516 Replace oulet cover	Mar-11	4143-1
500	517 Replace drip pans	War-11	4152-1
500	517 Paint bathroom ceiling	l l'alar.	4144-1
500	518 Replace drip pans	Mar-11	4145-1
200	518 Rolace blinds in both livrm /hedrm	Mar-11	4146-1
500	518 Replace eclectrical cover	War-11	4147-1
500	519 Replace drip pans	War-i i	4152-1
200	519 Caulk tub	Mar-11	4148-1
200	519 Replace blinds in hedrm	Mar-11	4149-1
200	519 Adjust hall closet door	Mar-11	4150-1
500	520 Bathrom axhauet fan is noisy	Mar-11	4151-1
200	520 Adinet half closed door	Mar-11	4153-1
200	522 Replace drin page	Mar-11	4154-1
500	522 Rathroom walls are noting	Mar-11	4156-1
500	522 Toilet leaking	Mar-11	4157-1
500	522 Panlace rieted DB cint	Mar-11	4158-1
200	500 Coult tuk	Mar-11	4159-1
200	500 Doubless change hand	Mar-11	4155-1
	JAZ INGUACE STOWER READ	Mar-11	4160-1
200	524 Replace drip pans	Mar-11	4161-1
200	524 Replace BR sink	Mar-11	4462-4
200	524 Replace shwer surround/ caulk	Mar.11	7462 4
			1.5

)

### MULLICA WEST 2010 Annual Unit Inspection 600 Building I

Date: 10-15-2010

UNIT #	REPAIR DESCRIPTION	W.O. # COMPLETION DATE
601	Bathrm: Resurface Tub Bedroom: Paint vent on ceiling	3888-1
	Exterior: Door Bell	3889-1
		3890-1
602	Living Area: Replace blinds in Lv. Rm, Bedrm Bathrm.: resurface tub	3891-1
	Stairs: hole in wall	3892-I
		3894-1
603	Kitchen: Replace drip pans Living Area: Replace blinds in Lv. Room, Bedroom	3895-1
	Storage Rm: patch around breaker box	3896-1
		3897-1
604	Kitchen: replace drip pans  Bathroom; caulk tub	3898-1
	Living Rm: interior door off track	3899-1
		3900-1
605	Bathrm: replace sink Living area: interior door off track	3981-1
		3982-1

UNIT #	REPAIRS DESCRIPTION	W.O. # COMPLETION
606	Bathrm: replace sink,	3903-1
	resurface tub	3904-1

607 Bathrm: replace surround 3905-1 Storage rm: close space around breaker box 3906-1 608 Exterior: Paint trim 3907-1 Kitchen: replace ventilation fan 3908-1 609 Bathrm: resurface tub 3910-1 Living area: door off track, all knobs are loose 3911-1 Kitchen: replace stem 3913-1 611 Bathrm: resurface tub 3916-1 Bedrm: paint and repair wall 3918-1 Replace knobs on closet doors 3919-1 Kitchen: replace stem 3920-1 612 Bedrm: tighten knob on both bedroom doors 3924-1 Bedrm: replace blinds in both bedrooms 3925-1 UNIT # REPAIRS DESCRIPTION W.O. # COMPLETION DATE Kitchen: replace drip pans 3926-1 613 Bathroom: replace aerator on sink 3927-1 Living Rm: replace blinds in both windows 3929-1 Kitchen: replace ventilation fan 3930-1 614 Bathroom: caulk tub 3931-1 615 Kitchen: caulk/seal counter top 3934-1 Kitchen: sink needs aerator 3935-1 Bathrm: caulk tub 3936-1 Bedrm: replace blind 3937-1 Bathrm: resurface tub 3939-1 616 drywall ceiling 3940-1 Living area: interior door; replace with proper size 3941-1 617

618		· · · · · · · · · · · · · · · · · · ·	
	i		

### MULLICA WEST 2010 Annual Unit Inspection 600 Building II

Date: 10-15-2010

UNIT #	REPAIR DESCRIPTION	W: O: # COM	
619	Kitchen: drywall damage Living Rm: replace damaged drywall around ceiling	3944-1	
	vent	3946-1	
	Living area: stairway upper wall has hole	3947-1	
620	Kitchen: replace tile floor Bathrm: wall has holes from towel bar	3948-1	
ī	Living area: Livrm and hall closet off track	3949-1	
<del></del>		3950-1	
621	Bedroom: replace closet light Living area: replace blinds in both livrm and bedrm	3951-1	
-		3952-1	

### MULLICA WEST 2009 Annual Unit Inspection 600 Building III

Date: 11/23/09

UNIT #	REPAIR DESCRIPTION	W. O. #	COMPLETION DATE
622	Kitchen: replace exhaust fan Bathrm: replace drain	3954-1	
	Tub faucet hard to turn on	3956-1 3955-1	
623	vacant	3933-1	
624	Bathroom: ventilation fan is hanging Living Rm: wall is damaged	3957-1	
	Bedroom: replace blinds and screens in both bedrooms	3960-1	
	Out Out S	3961-1	•

## 2010 Annual Unit Inspection Report - MULLICA WEST

### Date AUI Completed:12/1/2010

,

;	on Date Completion Date W.O. #	Mar-11 4169-1	Mar-11 4170-1	Mar-11			Mar-11	Mar-11	Mar-11						Mar-11 4192-1	Mar-11	Mar-11		Mar-11 4196-1	Mar-11	Mar-11 4198-1		Mar-11 4201-1	Mar-11 4202-1	Mar-11 4203-1	
Comments	rarget completion Date					S										IIIe	Xture	nd bedrm #2	1.1		V17	rm #2				_
Bldg # Apt. #						700 ZOO Deploy din 2000			700 ZOO Berless BD sink					700 713 Replace kitch counterfor											700 719 Caulk tub	

}

	4206-1	4207-1		1-208-1
700 722 Replace drip pans	700 724 Replace drip page	din populari	/ UD / 724 Replace blinds in bedrm #1	INCL 1

i t

### **MULLICA WEST APARTMENTS**

### 2010 ANNUAL UNIT INSPECTION SCHEDULE

May 2010 Building One and Two

June 2010 Building Three and Four

July 2010 Building Five and Six

August 2010 Building Seven

From:

Mullica West Admin Assistant (MullicaWestAssistant@comcast.net)

Sent: To:

Wednesday, July 06, 2011 1:41 PM

Subject:

'Mullica West Property Manager' AUI Summary 2011 BLDG 100

### 2011 Annual Unit Inspection Report - MULLICA WEST APARTMENTS

Date AUI Completed: 6-16-2611

Bidg#	Apt.#	Comments	Target Completion Date	Completion Date	18/ 0 /
100	101	Replace kitchen cabinets	Sep-11	COmpletion Date	W.O. #
100	101	Shampoo carpet	Sep-11		4765-1 4766-1
100	102	Paint unit Replace bathroom sink faucet	Sep-11		4767-1
100	102	Coulk tub	Sep-11		4788-1
100	103	Replace bathroom sink	Sep-11		4769-1
100	105	Bathroom sink pop-up	Sep-11 Sep-11		4770-1
100	106	Bathroom sink pop-up	Sep-11		4771-1
100	106	Resurface tub	Sep-11	<del> </del>	4772-1
100	107 109	Replace drip-pans	Sep-11	· · · · · · · · · · · · · · · · · · ·	4773-1 4774-1
100	109	Bathroom faucet leaks	Sep-11		4775-1
100	109	Catilik tub Replace bethroom fixture	Sep-11		4776 1
100	110	Replace deliboral indure	Sep-11		4777-1
100	110	Resurface tub	Sep-11		4778-1
100	111	Replace drip-pans	Sep-11 Sep-11		4779-1
100	111	Adjust refrigerator doors	Sep-11		4780-1
100	111	Caulk tub	Sep-11		4781-1 4782-1
100	112 112	Replace drip-pens	Sep-11		4783-1
100	112	Replace range hood light bulb	Sep-11		4784-1
100	113	Adjust bi-fold door bedroom #1 Kitchen sink leek	Sep-11		4786-1
100	113	Replace tolet	Sep-11		4786-1
100	114	Replace drip-pans	Sep-11	<u> </u>	4787-1
100	114	iGichen faucet leaks	Sep-11 Sep-11		4789-1
100	114	Replace bethroom sink	Sep-11	······································	4788-1
100	114	Adjust bi-fold door bedroom #2	Sep-11		4790-1
100	115	. Replace range flood light bulb	Sep-11		4791-1 4792-1
100	115 118	Replace entry doorbell	Sep-11		4793-1
100	116	Replace frig crisper	Sep-11		4794-1
100	118	Kitchen faucet leake Replace range hood light bulb and cover	Sep-11		4795-1
100	116	Totlet continually runs	Sep-11		4796-1
100	118	Replace drip-pane	Sep-11 Sep-11	1	4797-1
100	118	Kitchen faucet laaks	Sep-11		4799-1
100	119	Replace kitchen light fixture cover	Sep-11		4800-1
100 100	119	Range hood exhaust is noise	Sep-11	· · · · · · · · · · · · · · · · · · ·	4801-1 4802-1
100	120 120	Replace kitchen light fluture cover	Sep-11		4804-1
100	121	Replace entry doorbell	Sep-11		4805-1
100	123	Adjust livroom bi-fold door handle Replace range hood light cover	Sep-11		4806-1
001	123	Replace bethroom floor	Sep-11		4807-1
100	123	Replace bathroom sink stopper	Sep-11		4808-1
100	123	Replace blinds in both bedrooms	Sep-11 Sep-11		4609-1
00	123	Replace fover floor	Sep-11		4811-1
00	124	Repair bathroom light foture	Sep-11		4812-1 4813-1
00	124	Adjust bi-fold door bedroom #1	Sep-11	<del></del>	4814-1
<del> -</del>	_				
1	<del></del>				
	1_				
_					
1	3			<u> </u>	

# 2011 Annual Unit Inspection Report - PROPERTY NAME

### Date AUI Completed:

W.O.#	5132-1	5133-1	5133-2	5134-1	5134-2	5134-3	5135-1	5135-2	5136-1	5136-2	5137-1	5137-2	5138-1	5138-2	5138-3	5138-4	5139-1	5139-2	5139-3	5139-4	5140-1	5141-1	5141-2	5141-3	5142-1	5143-1	5143-2	5144-1	5144-2	5145-1	5145-2	5146-1	5147-1	5147-2
Completion Date																																		
Target Completion Date	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-11	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12
	FAUCAT AND DRAIN LEAKS	REPAIR CLOSET KNOB	REPLACE BLINDS IN BOTH BESDROOMS	REPLACE DRIP PANS	CAULK TUB	BR 2 ADJUST BIFOLD DOOR	CAULK TUB	RREPAIR ENTRANCE DOOR KNOB	REPLACE RANGE HOOD EXHAUST FAN	REPLACE HALL LIGHT FIXTURE COVER	REPAIR KITCHEN FAUCET	CAULK TUB	REPLACE FRIG BULB	ш	CAULK TUB	REPLACE LIVRM BLIND	REPAIR RANGE HOOD LIGHT	REPLACE BATHROOM SINK	REPAIR BEDROOM CLOSET DOOR	REPAIR ENTRANCE DOOR KNOB	REPAIR KITCHEN FAUCET	REPAIR KITCHEN DRAWER	CAULK TUB	ADJUST BEDROOM 2 BIFOLD DOOR	CAULKTUB	ADJUST LIVROOM BIFOLD DOOR	REPLACE EXTERIOR DOOR WEATHER STRIP	REPAIR HOLE ON STAIRWAY WALL	REPAIR HALL CLOSET DOOR KNOB	REPAIR HALL CLOSET DOOR KNOB	REPLACE DOOR BELL	ADJUST HALL BIFOLD DOOR	REPLACE BATHROOM SINK	REPAIR LIVROOM BIFOLD DOOR
Apt.#	201	201	201	202	202	202	203	203	205	205	206	206	207	207	207	207	209	209	209	209	210	211	211	211	212	213	213	214	214	215	215	216	217	217
Bldg #	200	200	200	200	200	200	200	200	200	200	200	200	200	200	200	200	200	200	200	200	. 200	200	200	200	200	200	200	200	200	200	200	200	200	200

S
₹
S
æ
ğ
ш

,

.

5147 2	0-74-0	5147-4	5148-1	5148-2	5148-3	0-01-0 1-01-01-01-01-01-01-01-01-01-01-01-01-01	E440 0	Z-0410	5149-3	5150-1	5151-1	R4R4_0	7,000	200	5151-4	5152-1	5152-2
Mar-12	7 T T T T	ווומו– ול	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	7) IS:	War-12	Mar-12	Mar-12	Mar-12	Mar.12	1440	War-12	Mar-12	Mar-12
REPLACE HOT WATER HEATER	REPAIR HALL CLOSET DOOR KNOR	1000 HOOLE 7 HOO	CAULK IUB	SHAMPOO CARPETING	REPAIR HALL CLOSET DOOR KNOB	REPAIR RANGE BURNER	SHAMPOO CARPETING	RED! ACE REDROOM B! IND	יייי ייייי ייייי יייייי יייייייייייייי	KEPAIK KITCHEN FAUCET	REPLACE RANGE HOOD EXHAUST FAN	REPAINT BATHROOM DOOR	REPLACE BOTH BEDROOM BLINDS	PEDI ACE STODAGE LIGHT STOINS		CAULK TUB	PAINT CEILING STAINS
217	217	218	210	218	218	221	221	221	1000	777	223	223	223	223	2 2	224	224
200	200	200	200	200	200	200	200	200	000	200	200	200	200	200	200	200	200

# 2011 Annual Unit Inspection Report - PROPERTY NAME

### Date AUI Completed: 8-9-2011

}

7 0 3	*.C.*	5156-1	5157-1	5157-2	5158-1	5158-2	5159-1	5160-1	5161-1	5162-1	5162-2	5162-3	5163-1	5153-2	5164-1	5181-1	5181-2	5181-3	5181-4	5165-1	5165-2	5166-2	5166-4	5166-1	5166-3	5166-5	5167-1	5167-2	5168-1	5168-2	5168-3	5168-4	5169-1	5169-2	5169-3
Completion Deta	Completion Date																											To the state of th							
Target Completion Data	Apr. 14	Apr. 1	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11
Comments	REPLACE DRIP PANS	CAIIIKTIB	REPAIR BRICK MOLDING	REPAIR BACK I BET DANCE BI IDNED	DEDI ACIT LE L'ANGE DONINER	DEDLACE DINCE LOCATION DESIGNATION DESIGNATION DE DINCE DANICE LOCATION DE LA PROPERTIE DE LA	NETLACE ARINGE HOUD BOLB	DEBAID VITO PROPERTY	REPAIR NI CHEN SINK UKAIN	REPAIK DKAIN PIPE	REPLACE COLD AIR RETURN VENT	KEPAIK BKICK MOLDING	KIICHEN FAUCEI LEAKS	KEPLACE WEATHER		쁴	REPLACE ALL BLINDS	REPLACE EXTERIOR LIGHT FIXTURE	മ	CAULK TUB	ADJUST LIV RM BIFOLD DOOR & REPAIR BDRM CLOSET KNOB		REPLACE KITCHEN FAUCET CARTRIDGE	RESURFACE TUB	REPLACE ALL WINDOW SILLS	REPLACE ALL BLINDS	REPLACE KITCHEN SINK CARTRIDGE	REPLACE STORAGE LIGHT FIXTURE STRING	REPLACE RUBBER SEAL ON FRIG DOOR	REPLACE DRIP PANS	REPLACE KIITCHEN LIGHT COVER	RESURFACE TUB	REPAIR KITCHEN FAUCET	REPLACE RANGE HOOD LIGHT COVER	ADJUST HALL CLOSET DOOR
Apt. #	301	301	301	303	303	304	305	302	300	000	300	300	300	308	010	311	115	311	311	312	312	314	314	314	314	314	315	315	316	316	316	316	317	317	317
Bldg #	300	300	300	300	300	300	300	300	300	200	2000	300	200	000	000	000	000	300	300	300	300	300	300	200	300	300	300	300	300	300	300	300	300	300	300

REPLACE ALL BLINDS REPLACE WATER HEATER REPLACE KITCHEN SINK CARTRIDGE REPLACE KITCHEN SINK CARTRIDGE REPLACE KITCHEN SINK CARTRIDGE REPLACE ENTY SWOWER ROD REPLACE ENTY SWOWER ROD REPLACE ENTY SWOWER ROD REPLACE BATHROOM FAUCET REPLACE BATHROOM FAUCET REPLACE BATHROOM FAUCET REPLACE BATHROOM FAUCET REPLACE EXTENDEL Apr-11 REPLACE FRIG CRISPER SHELF REPLACE FRIG CRISPER SHELF REPLACE FRIG CRISPER SHELF REPLACE EXTENDEL IGHT BULB REPLACE KITCHEN LIGHT COVER REPLACE SAFEL DOOR KNOB REPLACE SHED DOOR LOCK Apr-11 REPLACE SHED SHELF APR-11 REPLACE SHELF APR	4 0440	6470.0	21/0-2 5470-2	51774 4	5171-2	51712 5474-2	6-1 1-0	1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	51716	5171-0	1-7/10	5172-2	5-21-C	5173-1	5173-2	5173-3	5173-4	5173-5	5174-1	5174-2	5174-3	5175-1	5175-2	5175-3	5175-4	5175-5	5175-6						
REPLACE ALL BLINDS  REPLACE HOT WATER HEATER  REPLACE KITCHEN SINK CARTRIDGE  REPLACE KITCHEN SINK STRAINER  KEPLACE BENT SHOWER ROD  REPLACE BENT SHOWER ROD  REPLACE SWOKE DETECTOR  ADJUST FRIG DOOR  REPLACE SANGE HOOD BULB  REPLACE RANGE HOOD BULB  REPLACE RANGE EXHAUST FILTER  REPLACE RANGE EXHAUST FILTER  REPLACE RANGE EXHAUST FILTER  REPLACE RANGE EXHAUST FILTER  REPLACE KITCHEN LIGHT BULB  REPLACE KITCHEN LIGHT BULB  REPLACE KITCHEN LIGHT BULB  REPLACE KITCHEN LIGHT BULB  REPLACE KITCHEN LIGHT COVER  REPLACE KITCHEN LIGHT COVER  REPLACE BATHROOM SINK  REPLACE BATHROOM BOOR KNOB  REPLACE SHED DOOR LOCK  REPLACE SHED DOOR LOCK	Anr.11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Anr.11	A 25. 14	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11	Apr-11						
	REPLACE ALL BLINDS	REPLACE HOT WATER HEATER	REPLACE WEATHER STRIP	REPLACE KITCHEN SINK CARTRIDGE	REPLACE KITCHEN SINK STRAINER	KITCHEN SINK LEAKS	REPLACE BENT SHOWER ROD	REPLACE ALL BLINDS	RELACE SMOKE DETECTOR	ADJUST FRIG DOOR	REPLACE RANGE HOOD BLILB	REPLACE BATHROOM FAUCET	REPLACE DOOR BELL	REPLACE FRIG CRISPER SHELF	REPLACE KITCHEN LIGHT COVER	REPLACE RANGE EXHAUST FILTER	REPLACE ALL BLINDS	REPLACE EXTERIOR LIGHT BULB	REPLACE KITCHEN LIGHT BULB	REPAIR BATHROOM CEILING DAMAGE	REPAIR BATHROOM SINK	REPLACE KITCHEN LIGHT COVER	REPLACE BATHROOM DOOR KNOB	REPAIR LIV CLOSET DOOR KNOB	REPAIR BEDROOM #2 CLOSET DOOR KNOB	REPLACE HALL LIGHT COVER	REPLACE SHED DOOR LOCK						
	300	300	300	300	300	300	300	300	300	300	300	300	300	300	300	200	300	300	300	300	300	300	300	300	300	300	300				•		

## 2011 Annual Unit Inspection Report - MULLICA WEST

Date AUI Completed: 12-2-2011

Γ	Т	7	_			ı –	Г	Т	T	1	Т	Т	<u> </u>	Т	Т	7	7			т	т	Т	<del></del>	Т	Т	т.	_	Τ.	Т	Т	т	Τ.	т-	
# O M	F 5 10 10 10 10 10 10 10 10 10 10 10 10 10	1-8070	5258-2	5258-3	5258-4	5259-1	5260-1	5280-2	5260-3	5284 4	5262-1	1-2020																						
Completion Date																																		
Target Completion Date	Mar.12	21-18M	71-1M	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12	Mar-12							W					The state of the s											
Comments	REPLACE BATHRM FLOOR	REDIACE REDRING	REPLACE RATTERVISMOKE DETECTOR	MISTALL TUDESLICE DEVELOR	INCIDE TITRESPECE ANOTHER	DEPLACE BOLLOW OF KICH CABINEL	KEPLACE KITCH SINK PLUMBING	REPLACE BATHRM EXHAUST FAN	REPLACE HOT WATER HEATER	REPLACE CRISPER SHELF	ADJUST LIVRM CLOSET DOOR																							
Apt. #	403	403	403	403	405	207	400	406	406	407	409																							
Bldg #	400	400	400	400	400	200	3 5	400	400	400	400																							<del></del>

## 2011 Annual Unit Inspection Report - Mullica West

### Date AUI Completed: 8/12/2011

# 0 %	#	1-2126	7-7170	5-7170	5213-1	2513-2	5513-3	5214-1	521E-4	5215-1	5215	5215-4	5218-1	5218-2	5219-1	5219-2	5219-3	5219-4	5220-1	5220-2	5220-3	5220-4	5221-1	5221-2	5221-3	5221-4	5222-1	5222-2	5224-1	5224-2	5224-3	5224-4	5225-1	5225-2
Completion Date																																		
Target Completion Date	Mav.12	May-12	May-12	Movedo	May-12	May-12	Max.10	Mav-12	Mav-12	Mav-12	Mav-12	May-12	Mav-12	Mav-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12	May-12
Comments	REPLACE BATHROOM EXHAUST FAN	PAINT BEDROOM WALLS	REPLACE BEDROOM SILL	RESURFACE TUB	ADJUST LIVROOM BIFOLD DOOR	ADJUST BEDROOM BIFOLD DOOR	REPLACE ALL BLINDS	ADJUST BEDROOM BIFOLD DOOR	REPLACE DRIP PANS	REPLACE CARTRIDGE KTCH SINK	REPLACE TOILET	REPLACE CARTRIDGE BATHRM SINK	REPLACE CARTRIDGE BATHRM SINK	RESURFACE TUB		REPLACE HOT WATER HEATER	REPLACE BREAKER FOR DRYER	WATER STAIN HALL CEILING	REPLACE CARTRIDGE KTCH SINK	REPLACE TOILET	CAULK TUB	REPLACE FOYER TILE	REPLACE DRIP PANS	CAULK TUB	REPLACE ALL BLINDS	REPLACE 2 SPACERS IN BREAKER BOX	REPLACE DRIP PANS	REPLACE BEDROOM BLINDS	REPLACE RANGE HOOD LIGHT COVER	ADJUST HALL BIFOLD DOORS	REPAIR MOLD ON BATHROOM CEILING	REPAIR HOLES ON BEDROOM CLOSET CEILING	REPLACE FRIG CRISPER SHELF	RESURFACE TUB
Apt.#	412	412	412	413	413	413	414	414	415	415	415	415	416	416	417	417	417	417	418	418	418	418	419	419	419	419	420	420	421	421	421	421	422	422
Bidg #	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400

0 3003	2772-3	5225-4	2225-4	1-977C	2-0770	5226-3	2220-4 5036 E	5220-5 5226-6	5226-7	5026	5220-0	5227.2	5757 2	5227.4	5227-F	2551													
													The second secon										The state of the s						
May-12	May-12	May-12	May-12	May-12	Mey 12	Mav-12	Mav-12	May-12	Mav-12	May-12	Mav-12	Mav-12	Mav-12	May-12	Mav-12														
REPLACE ALL BLINDS	REPLACE DOOR BELL	REPLACE STRING ON BEDROOM CLOSET LIGHT FIXTURE	REPLACE DRIP PANS	REPLACE CARTRIDGE KTCH SINK	RESURFACE TUB	REPLACE SHOWER SURROUND	REPAIR WATER DAMGE ON LIVRM WALLS	REPLACE LVRM WINDOW SILL	REPLACE BOTH BEDRM BLINDS	REPAIR ATTIC ACCESS PANEL	REPLACE DRIP PANS	REPLACE BATHRM SINK	RESURFACE TUB	REPLACE ALL BLINDS	REPLACE SMOKE DETECTOR														
422	422	422	423	423	423	423	423	423	423	423	424	424	424	424	424														
400	400	400	400	400	400	400	400	400	400	400	400	400	400	400	400										1				

)

## 2011 Annual Unit Inspection Report - Mullica West

### Date AUI Completed: 8-16-2011

	₩.O.*	5228-1	5228-2	5228-3	5228-4	5229-1	5230-1	5230-2	5231-1	5231-2	5232-1	5231-2	5231-3	5233-1	5233-2	5234-1	5234-2	5234-3	5235-1	5236-1	5236-2	5236-3	5237.1	3237-2	5237-3	5237-4	5237-5	5238-1	5239-1	5239-2	5239-3	5239-4	5240-1	5241-1	5242-1
- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	Completion Date																																		
Target Completion Date	arget completion bate	21-1Ju	Jun-12	ZI-unc	2L-unc	Jun-12	71-unr	Jun-12	Jun-12	71-unc	Jun-12	Suil-12	21-ling	ZI-INO	ZI-unc	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12
Comments	REPAIR ROCKING TOIL ET		REPLACE RATHRM EXHALIST EAN	REPAIR RORM #2 SCOTEN	REPLACE HOT WATER HEATER	REPLACE KITCH SINK NITT	REDIACE BATUDIA CINIC	REDI ACE DANS	RFPI ACE TOIL ET	REPLACE DRIP PANS	REPAIR KITCH FAUCET	REPAIR HALL BIFOLDS	REPLACE ALL BLINING	REPAIR HAII RIEGI OS	DEDI ACE VITCU CI OCO	דוסייגיי דייסיי דייסיי ביאס מיאסמס			INSPECT KITCH PLUMBING	KEPAIR FAUCET	CAULK TUB	REPLACE BATHRM EXHAUST FAN	REPLACE TOILET	REPLACE BATHRM EXHAUST FAN	ADJUST BEDRM #1 BIFOLD DOORS	REPLACE ALL BLINDS	REPAIR STORAGE DOOR MOLDING	REPLACE DRIP PANS	REPLACE DRIP PANS	_	REPAIR TOILE	ADJUST/REPAIR HALL CLOSET BIFOLDS AND HWH CLOSET KNOB	REPLACE DRIP PANS	REPLACE DRIP PANS	ADJUST HALL BIFOLDS
Apt. #	501	501	501	501	502	503	503	504	504	505	505	505	506	506	507	507	507	200	200	SOC S	609	509	513	513	513	513	513	516	218	518	1		519	520	179
Bldg #	200	200	200	200	200	200	500	200	200	200	200	200	200	200	200	500	200	000	000	36	one -	006	000	200	000	000	350	200	000	200	200	200	200	200	200

S
ť
3
9
2

.

-		_		_	 _	_	
, 0, 0,	5243-1	7 7 7 7 7 7 7	1-4470				
10 de 1	21-120	21-12	21.1700				
REPLACE ALL BLINDS		REPLACE BALTERM SINK SICHTER					
522	572	020					
റ്റാ	202	3					

## 2011 Annual Unit Inspection Report - MULLICA WEST

### Date AUI Completed: 12-2-2011

The state of the s	₩.O.₩	5263-1	5264-1	5265-1	5265-2	5265-3	5266-1	5266-2	5267-1	5268-1	5282-1	5270-1	5271-1	5271-2	5271-3	5271-4	5271-5	5271-6	5272-1	5272-2	5273-1	5274-1	5274-2	5274-3	5275-1	5276-1	5276-2	5278 2	2-0170	02/04	0-0/70	5277-1	5277-2	5277-3	5278-1	5278-2
	Completion Date																																			
T	larger completion Date	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	ZL-unc	ZL-unc	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	Jun-12	hin-40	71-IIIO	ZL-unc	Jun-12	Jun-12	Jun-12
Comments	CALEX LIB	REDI ACE KITCH CALICET	RED! ACE BATUDIN SINIC	REPLACE HOT WATER HEATER CLOSET DEVANALL	REDIACE DOOD BELL	REPLACE BESTIGEDATION	REPLACE BATHEM SINIX	RETADE CENTRAL	REDIACE RATHEM SINK	CALIF TIR	ADJUST I IVRM CLOSET DOOR	REPLACE RANGE HOOD EAN MOTOD		REPAIR TO II CT	DEDIACE SOABINE!	AD II IST DEDBM #2 DISCI	DEED! AOT SWOOT RETTENDED	ACTLACE GWOKE DELECTOR	REPLACE CARTRIDGE BATHRM SINK	REPLACE HALL LIGHT FIX LURE	KEPLACE HO! WA!ER HEATER RELIEF VALVE	REPLACE CARTRIDGE BATHRM SINK	REPLACE COVER BAIHRM EXHAUST FAN	HVAC/INSPECT CANDENSATE LINE	KEPAIR DRYWALL SOFFET/VENT	KEPLACE KIICH FLOOR	IGHTEN TOILET	KEPLACE BEDRIM CLOSET/LIGHT STRING	ADJUST LIVRM CLOSET DOOR	REPLACE ENTRANCE DOOR KNOB	INSPECT UNDER KITCH SINK CABINET(ODOR)	REPLACE RANGE HOOD FAN MOTOR	REDI ACE 3 DINI/CT	DEDI ACE EDIO ODIODEN SILILI	הבית האים האים האים האים האים האים האים האים	NET LACE CAR I RIDGE BA! HKM SINK
Apt. #	601	602	603	603	903	604	604	909	209	607	612	613	613	613	613	613	613	616	848	272	017	010	010	010	670	050	020	020	620	620	621	621	621	622	623	350
Bldg #	009	009	009	009	009	900	009	009	009	009	009	009	009	900	009	009	009	900	900	200	000		200	000	000	200	000	000	nna	900	009	009	009	009	900	

_					-,-	_		 	 	 			 	_
0 0101	5-8/20	52/8-1	5279-2	5279-3								The second secon		
lin-12	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	21 - 100	Jun-12	Jun-12										
RESURFACE TUB	REPLACE CARTRIDGE KITCH SINK	REDI ACE TOIL ET TANK	A DILIOT DICOL DOCUMENTO A	ADJUST BIFULD DOUKA BOTH BEDRMS										
622	623	623	503	023								•		•
900	009	009	008	3										•

## 2011 Annual Unit Inspection Report - MULLICA WEST

### Date AUI Completed: 12-5-2011

# 0 3	E20E 1	1-0202	5265-2	5286.1	5287.1	5288-1	5308-1	5290-1	5290-2	5290-3	5290-4	5290-5	5291-1	5292-1	5293-1	5294-1	5296-1	5296-2	5301-1	5301-2	5301-3	5302-1	5303-1	5304-1	5304-2	5304-3	5305-1	5306-1	5307-1	5307-2		
Completion Date	32																															
Target Completion Date	Jul-12	111-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12	Jul-12		
Comments	FIX NAIL POPS	CAULK BACKSPLASH	ADJUST BOTH BEDROOM BIFOLD DOORS	HOT WATER HEATER PIPE LEAKING	CAULK BATHROOM	REPLACE CRISPER SHELF	BATHRM CEILING VENT MISSING	REPLACE CARTRIDGE BATHRM SINK	REPAIR KITH DRAWER	REPLACE RANGE HOOD LENS	REPAIR KNOB HALL CLOSET	REPLACE ENTRANCE DOOR TRIM	REPAIR KITH WALL	REPAIR BATHRM SINK	CAULK TUB	REPLACE BTHRM EXHAUST FAN	REPAIR BEDRM DOOR KNOB	REPAIR BEDRM CEILING VENT	REPLACE KITH FAUCET	REPLACE HOT WATER HEATER	REPLACE SMOKE DETECTOR BATTERY	RANGE NEEDS DRIP PANS	REPAIR BREAKER BOX DOOR	KITH FLOOR DAMAGED	REPLACE CARTRIDGE KITH SINK	REPAIR HALL CLOSET BIFOLD DOOR	ADJUST HALL BIFOLD DOOR	REPAIR BEDRM BIFOLD DOOR	REPAIR KITH DRAWER	REPLACE RANGE HOOD FILTER AND LENS		
Apt. #	702	702	702	703	704	705	705	706	706	902	706	206	708	709	711	712	712	712	714	714	714	715	718	719	719	719	720	723	724	724		
Bldg #	700	200	200	700	700	200	700	200	700	200	700	700	200	00/	200	200	200	90,	9	00/	00/	700	700	700	200	700	700	700	200	700		



### STEVEN • S • COHEN • ARCHITECT • P.C. •

Capital Needs Assessment Mullica West Apartments, Mullica Hill, NJ Performed by Steven S. Cohen Architects

15. DCA Reports

### NJ DCA INSPECTION **MULLICA WEST**

Inspection Date: August 8, 2012 Completion Date:

	on Date:		
Bldg/Unit	Violations	Date Completed	Work Order#
Bidy/Offic	Violations  Violations	Octriple ted	Older #
Jnit 116	Bath-paint ceiling/wall		
Jnit 117	Bath-paint ceiling/wall		
Jnit 124	Bath-paint ceiling/wall		
	Bath-replace/repair tub		
	Kitchen-repair/replace floor covering,	ļ,	
	Kitchen-repair bath/toilet room ventilation exhaust system to comply with min req	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 :00
	for the exhausting of 50 cubic ft of air/minute	I lalace (1)	6103-1
	Living room-repair or replace electrical outlet	13136112	le102-1
Init 106	Bath-repair/replace tub hardware	70,50	
Jnit 110	Apt unit-paint entire dwelling unit Seedule Parat 123-12	12-5-12	6866-1
Init 114	Apt unit-correct damage caused by occupant		
	Apt unit-paint entire dwelling unit		
nit 118	Hall-replace s/d	8-8-201a	59917
	Apt unit-replace floor covering		
	Bath-paint ceiling		-
	Water heater room-provide hot water pressure relief discharge pipe within a		
	maximum of 20 inches from floor	12-18-1	6094
nit 121	Hall-replace or repair smoke detector	マイシの	2003-1
nit 122	Bath-repair/replace bathroom toilet		
	Building 2		
nit 201	Hall-replace s/d	8-8-3013	5993-1
]	Kitchen-repair faucet, leak repair	11-5-2012	1599 32
	Apt unit-improve housekeeping		
	leat closet-storage, move 3 ft away from heat equip	8-3(20)	RESIC
nit 214	Bath-maintain plumbing fixtures in clean and sanitary condition		
	leat closet-storage, move 3 ft away from heat equip	9202012	1-1-682
	Kitchen-repair/replace floor covering,		
	Bed 2-repair/provide heating equipment vent		
	Bed 2-repair heating equipment to maintain good operating condition free of	1	
	lefects, corrosion and deterioration		
		11-57-3019	.6058-1
	Stairway-repair/provide railing		
	leater room-storage move 3ft away from heat equip		
	(itchen-repair/replace floor covering,		
it 219   F	ront door-repair/replace door, hardware		
	Bulloino 3		
terior R	lepair leader to direct storm water away from building foundation walls		
	ath-paint ceiling		
	eat closet-reduce storage		
H	eat closet-storage, move 3 ft away from heat equip		
	ining room-repair or replace electrical switch	12-18-12	60957
	eater room-storage move 3ft away from heat equip		
	eater room-reduce storage	~ 0	
	all-replace s/d	8-8-2012	(-0000)
	pt unit-improve housekeeping		
	airway-exits, provide unrestricted passage	0-12-21-12	
err midden i	ot unit-continue rehab-vacant apt	8-10-5019	7018-1
	ot unit-continue rehab-vacant apt	9-20-2012	<del>19</del> 124-11

		16 1 2 - 3 ( ) 1 2 - A	
ტ <u>ის პაა</u> Apt 323	Apt unit-remove debris, bulk items	11-20-13	TENERALT
Apt 323	Apt unit-eliminate storage area	1000	
	Hall-replace s/d	8-8-2013	1-MM-1
	Stairway-exits, provide unrestricted passage	11-20-12	
2010/2014	Granway-exits, provide unrestricted passage		22.347
Designation of the second	Repair leader to direct storm water away from building foundation walls		
exterior_	Heat closet-provide access for inspection	<del>                                     </del>	
Jnit 404		11252012	6057-1
Jnit 408	Kitchen-repair stove, burners	11-15-2012	
Jnit 409	Hail-repair/replace closet  Heater room-provide hot water pressure relief dishcharge pipe within a maximum of		12/3/2°/
		11-28 2112	1727
	20 inches from floor		52/02-1
	Living room-repair/replace closet	11542 14	DECEDENT.
Jnit 413	Apt unit-replace floor covering	13 37-1	16097-0
	Bedroom-repair/replace door hardware Replaced 3 doors	8-12-2012	18175 H
Jnit 417_	Hall-replace/repair smoke detector	8 8-001V	6003-1
<u> Init 424</u>	Bedroom 2-paint ceiling 11/39/12 prepring, not painted yet	11-20 11	60044
	Front door-repair/replace door, hardware	11-30-13	
	Hall-replace/repair smoke detector	8-8-51/19	0004-1
	Hall-paint ceiling	155 00 10	161
	Kitchen-repair/replace kitchen cabinets	111-24-12	6055-1
	Kitchen-repair stove, burners	11-28-12	6055-1
Init 402	Bath-repair/replace floor covering	10-31-2012	5987-1
Init 403	Stairway-handrail, provide 1.5 finger clearance		
	Bath-repair bath/toilet room ventilation exhaust system to comply with min req for	111010	1, ,, , ,
Init 406	the exhausting of 50 cubic ft of air/minute	1179-12	
	Hall-replace s/d	8-8-5015	1005-L
nit 410	Front door-repair/replace door, hardware		
	Stairway-handrail, provide 1.5 finger clearance		
nit 415	Kitchen-repair floor covering, trip hazard	12-26-12	6097-1
nit 419	Front door-repair/replace door, hardware	12-1812	10056-
		Territoria de la constanta de	Complete Com
	E Bulting 15		
xterior			
xterior	Repair leader to direct storm water away from building foundation walls		
xterior	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk		
	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk	11-39-2012	)-Galoa
	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute	11-39-2012 11-39-2013	
nit 501	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes	W-2013	(1-600g)
nit 501	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes Heater room-reduce storage	11-1-2012 11-1-2012	(0062-1 Res
nit 501 nit 504	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes Heater room-reduce storage Heater room-storage move 3ft away from heat equip	W-2013	(0062-1 Res (EES)
nit 501 nit 504	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes Heater room-reduce storage Heater room-storage move 3ft away from heat equip Bedroom-paint ceiling/wall told. paid 12-3-13.	11-292012  11-1-2012  11-3-12	(062-1 Res (ES) 12162-1
nit 501 nit 504	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes Heater room-reduce storage Heater room-storage move 3ft away from heat equip Bedroom-paint ceiling/wall Solid. paint 12-3-13. Kitchen-repair/replace floor covering	11-1-2012 11-1-2012	(062-1 Res (ES) 12162-1
nit 501 nit 504 nit 505	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes Heater room-reduce storage Heater room-storage move 3ft away from heat equip Bedroom-paint ceiling/wall (shake) paint 12-3-13. Kitchen-repair/replace floor covering Bath-repair bath/toilet room ventilation exhaust system to comply with min req for	11-1-2012 11-1-2012 11-1-2012 11-3-12 10-23-2012	(0062-1 Res DES DES DES DES DES DES DES DES DES DES
nit 501 nit 504 nit 505	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall (Solid), paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute	11-1-2012 11-1-2012 11-1-2012 11-3-12 11-3-2112 11-1-1-2	(0062-1 1282-1 1282-1 1282-1 1282-1 1398-1
nit 501 nit 504 nit 505 nit 513	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes Heater room-reduce storage Heater room-storage move 3ft away from heat equip Bedroom-paint ceiling/wall (shake) paint 12-3-13. Kitchen-repair/replace floor covering Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-caulk/grout bathtub area	11-1-2012 11-1-2012 11-1-2012 11-3-12 10-23-2012	(0062-1 RES DES DES DES DES DES DES DES D
nit 501 nit 504 nit 505 nit 513	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes Heater room-reduce storage Heater room-storage move 3ft away from heat equip Bedroom-paint ceiling/wall (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	11-1-2012 11-1-2012 11-1-2012 11-3-12 10-23-2012 11-1-2012	10063-1 10063-1 15463-1 15463-1 15988-1 15988-1
nit 501 nit 504 nit 505 nit 513	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-secure toilet, bath shakes Heater room-reduce storage Heater room-storage move 3ft away from heat equip Bedroom-paint ceiling/wall (Solid), paint 12-3-13. Kitchen-repair/replace floor covering Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute Bath-caulk/grout bathtub area Bath-paint ceiling/wall Hall-replace or repair smoke detector	11-1-2012 11-1-2012 11-1-2012 11-3-12 11-3-2112 11-1-1-2	(0062-1 606-1 (006-1
nit 501 nit 504 nit 505 nit 513	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall (Solid), paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathtub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage	11-1-2012 11-1-2012 11-1-2012 11-3-12 10-23-2012 11-1-2012	(0062-1 RES. 15462-1 15462-1 15462-1 (006-1 (006-1
nit 501 nit 504 nit 505 nit 513	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall Shake paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathtub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-12 11-1-2012 8-8-2012	1006-1 1006-1 1006-1 1006-1 1006-1
nit 501 nit 504 nit 505 nit 513	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall Soled. paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathtub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-2012 11-1-2012 8-8-2012	(0062-1 Res. DI 62-1 DI 62-1 DI 82-1 GOG-1 6006-1 6006-1 6006-1 1006-1
nit 504 nit 505 nit 513 nit 516	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall (2)(2), paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathtub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-12 11-1-2012 8-8-2012	(0062-1 Resident FUGE-1 FUGE-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1
nit 504 nit 505 nit 513 nit 516 nit 524	Repair leader to direct storm water away from building foundation walls Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall (slick), paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathtub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector  Apt unit-paint entire dwelling unit	11-1-2012 11-1-2012 11-1-2012 11-3-12 10-3-2012 11-1-2012 8-8-2012 8-8-2012	(0062-1 Resident FUG-1 FUG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1
nit 504 nit 505 nit 513 nit 516 nit 524 nit 502 nit 511	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall (bid. paint 12-3-1).  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathtub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector  Apt unit-paint entire dwelling unit  Apt unit-continue rehab-vacant apt  UNIT HAS BECALORS SINCE JACORS	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-12 11-1-2012 8-8-2012 8-8-2012 2-10-2012	(0062-1 Resident FUG-1 FUG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1
nit 504 nit 505 nit 513 nit 516 nit 524 nit 502 nit 511 nit 514	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall Skd. parat 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-eaulk/grout bathtub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector  Apt unit-paint entire dwelling unit  Apt unit-continue rehab-vacant apt Unit Hall-special Complex School Co	11-1-2012 11-1-2012 11-1-2012 11-3-12 10-3-2012 11-1-2012 8-8-2012 8-8-2012	(0062-1 Resident FUG-1 FUG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1 GOG-1
nit 504 nit 505 nit 513 nit 516 nit 524 nit 502 nit 511 nit 514	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall (a) (a) (a) (a) (b) (b) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-2012 11-1-2012 8-8-2012 8-8-2012 8-8-2012	(006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1 (006-1
nit 504 nit 505 nit 513 nit 516 nit 524 nit 502 nit 511 nit 514	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall Sold, paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathtub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector  Apt unit-paint entire dwelling unit  Apt unit-continue rehab-vacant apt UNIT HARS PROCADORS SIND SIND SIND SIND SIND SIND SIND SIN	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-2012 11-1-2012 11-1-2012 8-8-2012 8-8-2012 111-1-2012 10-2012 111-1-2012 111-1-2012 111-1-2012	(0062-1 RES- PAGE-1 1988-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1
nit 504 nit 505 nit 513 nit 516 nit 524 nit 502 nit 514	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall (Sikt), paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathfub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector  Apt unit-paint entire dwelling unit  Apt unit-continue rehab-vacant apt Unit Hall-seculous Sine Silve Si	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-2012 11-1-2012 8-8-2012 8-8-2012 8-8-2012	(0062-1 RES- PAGE-1 1988-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1
nit 504 nit 504 nit 505 nit 513 nit 516 nit 524 nit 502 nit 511 nit 514	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall Solid, paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-reduce storage  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector  Apt unit-paint entire dwelling unit  Apt unit-continue rehab-vacant apt UNIT HAS RECALORS SINE SINE SINE SINE SINE SINE SINE SIN	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-2012 11-1-2012 11-1-2012 8-8-2012 8-8-2012 111-1-2012 10-2012 111-1-2012 111-1-2012 111-1-2012	(0062-1 RES- PAGE-1 1988-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1
nit 504 nit 505 nit 513 nit 516 nit 516 nit 514 nit 519	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall (sh. paint 12-3-1).  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-caulk/grout bathitub area  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector  Apt unit-paint entire dwelling unit  Apt unit-continue rehab-vacant apt  Unit left Security Sine Sine Sine Sine Sine Sine Sine Sine	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-2012 11-1-2012 2-8-2012 2-8-2012 2-8-2012 11-5-2012 11-5-2012	(0062-1 RES- PAGE-1 1988-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1
nit 516  nit 524  nit 502  nit 511  nit 514  nit 519  nit 522	Repair leader to direct storm water away from building foundation walls  Units 506,510,516 repair/replace sidewalk  Bath-replace bath/toilet room ventaliation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-secure toilet, bath shakes  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Bedroom-paint ceiling/wall Solid, paint 12-3-13.  Kitchen-repair/replace floor covering  Bath-repair bath/toilet room ventilation exhaust system to comply with min req for the exhausting of 50 cubic ft of air/minute  Bath-paint ceiling/wall  Hall-replace or repair smoke detector  Heater room-reduce storage  Heater room-reduce storage  Heater room-reduce storage  Heater room-storage move 3ft away from heat equip  Front door-repair/replace threshold plate  Hall-replace or repair smoke detector  Apt unit-paint entire dwelling unit  Apt unit-continue rehab-vacant apt UNIT HAS RECALORS SINE SINE SINE SINE SINE SINE SINE SIN	11-1-2012 11-1-2012 11-3-12 11-3-12 11-1-2012 11-1-2012 11-1-2012 8-8-2012 8-8-2012 111-1-2012 10-2012 111-1-2012 111-1-2012 111-1-2012	(0062-1 RES- PAGE-1 1988-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1 1906-1

, ,	; 		
		1X10-001	HUPC P
Unit 601	Bath repair or replace week havin in half		
Unit 604	Bath-repair or replace wash basin in bathroom Heater room-reduce storage		(0008-1
OIIII 004			5774-1
Unit 612	Heater room-storage move 3ft away from heat equip Bath-reglaze tub	1831-3018	
Offic 012		10-5-2012	15929-1
<u> </u>	Bath-repair/replace faucet/basin		6010-1
	Kitchen-repair/replace refrigerator		6010-1
Unit 613	Kitchen-repair/replace stove	10.5290	15960-1
OUIT 6 19	Bath-reglaze tub	10-28-2012	1600g-1
	Kitchen-repair/replace refrigerator	8-21-201	5812-1
11-2-047	Kitchen-repair defective parts in refrigerator	8-21-2013	
Unit 617	Kitchen-repair refrigerator leak		6011-1
Unit 620	Apt unit-improve housekeeping		
11-11-004	Apt unit-remove illegal extension cords		
Unit 624	Bed 1 & 2-repair/replace door		6013-1
	Heater room-reduce storage		
	Heater room-storage move 3ft away from heat equip		
11 11 007	Heater room-repair door		
Unit 607	Bath-correct damage caused by occupant		
<u> </u>	Bath-reglaze tub		6012-1
	Bath-repair/replace shower wall	-	6012-1
Unit 623	Bath-repair toilet flush mechanism		1-6-100)
	BUIDING 7		
Unit 703	Repair/replace sidewalk		
Unit 704	Bath-secure toilet, bath shakes convicted	(12/19/12	) 60 Q2 -1
Unit 705	Front door-repair/replace threshold plate	12-18-18	1056-1
Unit 713	Bedroom rear-repair ceiling and locate source of leak	14 13 14	16177
	Bedroom rear-paint ceiling	-	
Unit 716	Apt unit-replace floor covering		·
	Apt unit-paint entire dwelling unit		<del></del>
Unit 717	Heater room-remove illegal extension cords		
Unit 724	Bath-repair wall and locate source of leak		
<u> </u>	Bath-paint ceiling		<del></del>

.

.

HATE OF INSP.

State of Rew Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS BUREAU OF HOUSING INSPECTION

### INSPECTION

PAGE NO.

REGISTRATION NO.

0808-10569-0

**ORDERS OF THE TYPE**\*

APTS\* UNITS\*

COMMISSIONER

TOTAL#

24. The second section is a second section to a

RECEIVED INSPECTOR\*

VERONICA S WOOD "

Consequence of the consequence o

MATE ISSUED DE 09/20/2012 MATE BY WHICH VIOLATIONS TUST BE CORRECTED:

\*\*\*BUILDING\*\* CRM

1 9 3 1 %

MULLICA WEST CONDO 58 WOODSTOWN RD

HARRISON, NJ 08098 

. . . . #

MULLICA WEST LTD C/O BART REST TO SO S MAINS STORES OF STORES OF STORES

08/08/2012

SESBO UN

for his tissee our collisions.

'ROPERTY CONTACT, PHONE NUMBER: 854-478-4422

BLDG NO. 001

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Fallure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	INSPECTION TYPE: VIOLATIONS	CODE CITATION	REINSPECTIO O-OPEN VIOL: A-ABATED
-	NOTE: IF ANY VIOLATIONS ARE PRECEDED BY A 'P', 'M' OR 'L', REFER TO THE PERMIT INFORMATION AT THE END OF THE REPORT.	្រា ម៉ូល្ប៉ូ អ្	
sara,	ALL CODE CITATIONS ARE PRECEDED BY 5:10, EXCEPT THOSE SEGINNING WITH THE NUMBER 4/ WHICH ARE PRECEDED BY 5:70.	ayeri Maria	
<del></del>	CODE CITATIONS BEGINNING WITH 6A OR 6B REFER TO APPENDICES 6-A AND 6-B OF N. J. A. C. 5: 10-6: 6.	1	ta larg
Letter Crace	ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C 5:70 ET SEQ.	. 500 2 . 700 100 1	184. S
1/2	UNIT: 116 YEW LOCATION CEILING/WALL PAINT BATH	8. 2	
5/5	UNIT: 117 VSW FLOOR 1	8.2	
3/2 4/2 5/2	UNIT: 124  GEILING/WALL PAINT  Tub, "replace/repair BATH  Floor covering, repair/replace KITCHEN	8.2 21.1(A) 8.2	
	CONTINUED PAGE 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

### State of Rew Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS BUREAU OF HOUSING INSPECTION

INSP. 09/08/2012 INSPECTION

PAGE NO.

REGISTRATION NO.

0808-10569-C

1.5

ORDERS OF THE TYPE\*

APTS\* UNITS\*

**MISSIONER** 

TOTAL\*

INSPECTOR\*

VERONICA & WOOD

,09/20/2012 DATE ISSUED DATE BY WHICH VIOLATIONS **1VST BE CORRECTED:** 

AXELROD

The second secon

TO DESCRIPTION \*\*BUILDING\*\*

MULLICA WEST CONDO 58 WOODSTOWN RD

HARRISON, NJ 08098

36 S MAIN ST PLEASANTVILLE NJ 08232

•

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

MULLICA WEST LTD C/O BART

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S. 4 55:13A-1 et seq.).

LINE #	VIOLATIONS	CODE CITATION	REINSPECTION O-OPEN VIOLS A-ABATED
6/2	M REPAIR BATH/TOILET ROOM VENTILATION EXHAUST KITCHEN SYSTEM TO COMPLY WITH MIN REG FOR THE EXHAUSTING OF 50 CUBIC FT OF AIR/MINUTE:	i 6:3 3 7 7	
7/2		(B) 1 (B)	5 1 5 5 5 T
8/2	UNIT: 106 VSW FLOOR 2 Tub, hardware repair/replace BATH	21.1(A)	
en een	UNIT: 110 YBW FLOOR 2		
A\K	L PAINT ENTIRE DWELLING UNIT.  UNIT: 114  VSW FLOOR 2	8.2(C)	į ,
10/2 11/2	[ <del>                                     </del>	5. 5 8. 2(C)	
· ·	UNIT: 118 YSW FLOOR 2		50
12/2	8/D, REPLACE HALL.	4, 9, 34	, j. 6
13/2	1 · · · · · · · · · · · · · · · · · · ·	8. 2	
14/2	GEILING, PAINT BATH PROVIDE HOT WATER HEATER PRESSURE RELIEF WATER HTR RM	8.2 (4.3(E)	
. (m	DISCHARGE PIPE WITHIN A MAXIMUM OF 20 INCHES		
	CONTINUED PAGE S ** ***		V / 1
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

PATE OF INSP.

INSPECTION

PAGE NO.

 $(s, \partial_{t}^{2}(g_{t}^{2}(s)), s, t) = (s, t) + (s, t) +$ 

State of New Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

08/08/2012

MULLICA WEST LTD C/O BART

36 S MAIN ST

PLEASANTVILLE

AXELROD

Communication of the Communica

ORDERS OF THE TYPE\*

APTS\* WHITE\*

0805-10569-0

OMMISSIONER

TOTAL\*

INSPECTOR\* VERONICA S WOOD

)ATE, 185UED ....07/20/2012.... DATE BY WHICH VIOLATIONS **1UST BE CORRECTED:** 

11/19/2012 

ar green was s

NY 08535

\*\*BUILDING\*\* 0808

MULLICA WEST CONDO SS WOODSTOWN RD HARRISON-CNJ 08098

REGISTRATION NO.

人名西斯特 阿波兰加州 化多元二十二烷

PROPERTY CONTACT PHONE NUMBER: 856-478-4422 BLDG. NO. 001 OF 007 BLDGS.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Fallure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	VIOLATIONS	* .	**************************************		CODE	REINSPECTION O-OPEN VIOLA-ABATED
	2.86% (3.00) (3.00)	÷ ;			1000	
16/2	<u>UNIT:</u> 121 REPLACE OR REPAIR SMOKE DETECTOR.	<u>vew</u> ;	<u>FLOOR</u> HALL	2	4. <del>9</del>	
17/2	<u>UNIT:</u> 122 Toilet, bathroom, repair/replace	VBW	FLOOR BATH	2	21.1(A)	!
	NO ADMITTANCE GAINED TO THE FOLLOW 113 115 123	IING AREAS	/UNITSpace			A STATE OF THE STA
	NO VIOLATIONS FOUND IN THE FOLLOW EXTERIOR AREAS COMMON 101 104 105 108 111 112 120 103 107 107		VUNITS:	e et la se		A B A A A A A A A A A A A A A A A A A A
İ	CONTINUED PAGE 4					
	en e	1. ·	의 4 기 년 11 (18 ) 기 대한 11 (18 ) 사 기계(18 )		A TO SERVE A TO SERVE TO SERVE	i grandi.
	e de la companya de		ı			
	"ATTENTION" - FURTHER INSTRUCTION					

INSPECTION

PAGE NO.

State of New Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

JATE OF INSP.

08/08/2012

ORDERS OF THE TYPE\*

APTS\*

UNITS\* TOTAL\* alta Siligaria

INSPECTOR\* VERONICA S WOOD

DATE ISSUED 09/20/2012 JATE BY WHICH VIOLATIONS **1UST BE CORRECTED:** 

Minimate not the second of the

MULLICA WEST LTD C/O BART AXELROD

MULLICA WEST CONDO 58 WOODSTOWN RD

HARRISON, NJ 08098

REGISTRATION NO.

36 9 MAIN ST PLEASANTVILLE

SES80 UN

NUMBER: 854-478-4422

was to the same of a

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	VIOLATIONS	CODE	REINSPECTION O-OPEN VIOLS A-ABATED
	'M' - A CONSTRUCTION PERMIT MAY OR MAY NOT BE REQUIRED		Sacrosco
	CONTINGENT UPON THE EXTENT OF THE REQUIRED WORK TO ABATE THE CITED VIOLATION(S). COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE CONSTRUCTION OFFICIAL'S APPROVAL OF WORK COMPLETED MUST BE PROMINENTLY DISPLAYED	ing the state of t	1
	IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE THE BUREAU OF HOUSING INSPECTION HAS COMPLETED IT'S REINSPECTION.	en in de gales en en en en en ender en <sup>en e</sup> n	(4) 5 1 (5) 5 1 2 3 (5) 4 5 2 3 (5) 5 5
	'L' - A CONSTRUCTION PERMIT MAY OR MAY NOT BE REQUIRED CONTINGENT UPON THE EXTENT OF THE REQUIRED WORK TO CORRECT THE CITED VIOLATION(S). IN THE EVENT THAT THE VIOLATIONS	e di Tito e i	
	ARE TO BE CORRECTED THROUGH LEAD ABATEMENT PURSUANT TO N.J.A.C. 5:17, A CERTIFIED LEAD ABATEMENT CONTRACTOR IS REQUIRED AND A CONSTRUCTION PERMIT MUST BE OBTAINED. COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE		1500 1500
	CONSTRUCTION OFFICIAL'S APPROVAL OF WORK MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE BUREAU OF HOUSING INSPECTION HAS COMPLETED ITS REINSPECTION. DOCUMENTATION FOR WORK	\$ 1.	
	PERFORMED BY A CERTIFIED LEAD ABATEMENT CONTRACTOR MUST BE MADE AVAILABLE TO THE BUREAU UPON REQUEST.	entre entre de la companya de la com	
	CONTINUED PAGE 5		2
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

State of Rew Tersey DEPARTMENT OF COMMUNITY AFFAIRS **DIVISION OF CODES AND STANDARDS BUREAU OF HOUSING INSPECTION** 

PATE OF INSP. 08/08/2012

### INSPECTION

PAGE NO. REGISTRATION NO.

0808-10569-C

RDERS OF THETYPE\* MD APTS\*

WRITS\* TOTAL\*

المعاف أالمعرفي الرا

INSPECTOR\* VERONICA S WOOD

MATE ISSUED 09/20/2012 NATE BY WHICH VIOLATIONS WET BE CORRECTED:

\*\*BUILDING\*\*

MULLICA WEST CONDO SS WOODSTOWN RD

HARRISON, NJ 08098

MULLICA WEST LTD C/O BART AXELROD

34 S MAIN ST FLEASANTVILLE

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 854-478-4422

 $(d_{i} = i, e_{i} = i)$ BLDG. NO. 001

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

INE #	VIOLATIONS	CODE	REINSPECTION O-OPEN VIO
	IF YOUR BUILDING WAS BUILT BEFORE 1978 AND IT IS NOT CERTIFIED AS BEING LEAD FREE ALL WORK PERFORMED TO ABATE PAINTING VIOLATIONS OR VIOLATIONS THAT DISTURB PAINTED SURFACES SHALL BE CARRIED OUT USING LEAD SAFE WORK PRACTICES BY INDIVIDUALS TRAINED IN ACCORDANCE WITH N. J. A. C. 5: 10-6.6(g). UPON RE-INSPECTION, THE PROPERTY OWNER MUST HAVE AVAILABLE FOR THE INSPECTORS REVIEW ANY TRAINING RECORDS TO SUPPORT COMPLIANCE WITH N. J. A. C. 5: 10-6.6(g), AS WELL AS ANY REQUIRED WIPE SAMPLES SHOWING THE WORK AREA TO BE LEAD HAZARD FREE. IF THERE IS DOCUMENTATION INDICATING THAT THE SURFACES CITED DO NOT CONTAIN LEAD BASED PAINT, THEN ALL WORK MUST COMPLY WITH N. J. A. C. 5: 10-8.2.  YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337, IF YOU REQUIRE ADDITIONAL INFORMATION.		
•	END VIOLATIONS	tuna 1 de la composición	1
	A CONTRACT OF THE CONTRACT OF	n communication of the second	
	and the second s		
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		

### INSPECTION

PAGE NO.

State of Rew Jersey DEPARTMENT OF COMMUNITY AFFAIRS **DIVISION OF CODES AND STANDARDS BUREAU OF HOUSING INSPECTION** 

)ATE OF INSP.

08/08/2012

MULLICA WEST LTD C/O BART

RDERS OF THE TYPE\* OMMISSIONER

APTS\*

0808-10569-0

UNITS\*

INSPECTOR\*

REGISTRATION NO.

VERONICA S MOOD

MATE ISSUED 09/20/2012 MATE BY WHICH VIOLATIONS **SUST BE CORRECTED:** 

11/19/2012

\*\*BUILDING\*\*

58 WOODSTOWN RD

Section & Form

article south

HARRISON, NJ 08098.

AXELROD. 36 8 MAIN ST

PLEASANTVILLE

NJ 08232

CONTACT PHONE NUMBER: 856-478-4422

1

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.# 55:13A-1 et seq.).

LINE #	INSPECTION TYPE: VIOLATIONS	CODE CITATION	REINSPECTIO O-OPEN VIOL A-ABATED
	NOTE: IF ANY VIOLATIONS ARE PRECEDED BY A 'P', 'M' OR' 'L''.  REFER TO THE PERMIT INFORMATION AT THE END OF THE REPORT.	E Single Fig.	
and of the	ALL CODE CITATIONS ARE PRECEDED BY 5:10, EXCEPT THOSE BEGINNING WITH THE NUMBER 4, WHICH ARE PRECEDED BY 5:70.	mondace, per Stron construction	nasanas Nasanas nasanas
Marina Marina	CODE CITATIONS BEGINNING WITH 6A OR 6B REFER TO APPENDICES 6-A AND 6-B OF N. J. A. C. 5:10-6.6.		
40-54 40-04 1-04-	ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C 5:70 ET SEQ.	e de la companya de l	
2/2 1/2	UNIT: 201 VSW LOCATION S/D. REPLACE HALL Faucet, leak repair WITCHEN	4. 9 21. 1(E)	
3/2	UNIT: 209  Housekeeping, improve  APT UNIT	5. 4	7 (1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
4/2	UNIT: 213  Storage move 3ft away of Heat equip.  CONTINUED PAGE 2	6. 1	
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

DATE OF INSP.

### INSPECTION

PAGE NO.

ORDERS OF THE **MISSIONER** 

APTS\*

0808-10569-0

UNITS\* TOTAL\* 2. . . . .

24.

INSPECTOR\*

REGISTRATION NO.

VERONICA S WOOD

JATE ISSUED 09/20/2012 SATE BY WHICH VIOLATIONS

**4UST BE CORRECTED:** 

\*\*BUILDING\*\*

58 WOODSTOWN RD

mar A Section

HARRISON, NJ 08078

AXELROD. 36 S MAIN ST.

PLEASANTVILLE

State of Rew Tersey DEPARTMENT OF COMMUNITY AFFAIRS

DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

08/08/2012

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 854-478-4422

MULLICA WEST LTD C/O BART

BLUG. NO. 002 OF 007

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Fallure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	VIOLATIONS	CODE CITATION	REINSPECTIO O-OPEN VIOL: A-ABATED
		=3.	100
5/2	<u>UNIT:</u> 214 <u>YSW</u> <u>FLOOR</u> 1 MAINTAIN PLUMBING FIXTURES IN CLEAN AND BATH	5.4	
1	SANITARY CONDITION	A A Mymark	
	UNIT: 216 VSW FLOOR 1	- n	].
6/2	Storage move 3ft away of Heat equip. HEAT CLOSET	6.1	
		1 10	
	UNIT: 218 YSW FLOOR 1		
.77,2	Floor covering, repair/replace KITCHEN	8.2	<del> </del>
	UNIT: 202 VSW FLOOR 2		14.57   13.44   1
8/2	Heating-equipment, vent, repair/provide BED 2	14.3	
9/2	REPAIR HEATING EQUIPMENT TO MAINTAIN GOOD BEDROOM 2	14.3	
*****	OPERATING CONDITION, FREE OF DEFECTS, CORROSION		
	AND DETERIORATION.	19.	
10/2	Stove, burners, repair KITCHEN	20.1(A)	
	UNIT: 210 YSW FLOOR 2		1 1
11/2		B. 4	
	<u>UNIT:</u> 212 <u>YSW - FLOOR</u> 2	1	
12/2	Storage move 3ft away of Heat equip. HEATER ROOM	6. 1	
	CONTINUED PAGE 3		1 1
	CONTINCED FAGE G		
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE	}	
	WITHING - LOKINEV MOLVOCHOMO ON WEARINGE GIPE	-	
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		
		1	1 1 1

INSPECTION

PAGE NO. REGISTRATION NO.

0808-10569-0

DEPARTMENT OF COMMUNITY AFFAIRS . DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

RDERS OF THE TYPE \*

APTS\* UNITS\*

COMMISSIONER

24

INSPECTOR\* VERONICA S WOOD

PATE ISSUED DATE BY WHICH VIOLATIONS

JATE OF INSP.

09/20/2012

08/08/2012

State of New Jersey

**4UST BE CORRECTED:** 

\*\*BUILDING\*\*

MULLICA WEST LTD C/O BART

AXELROD 36 8 MAIN ST

PLEASANTVILLE

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 856-470-4422

58 WOODSTOWN RD

HARRISON, NJ 08098

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.). 55:13A-1 et seq.).

LINE #	VIOLATIONS		CODE	REINSPECTIO O-OPEN VIOL A-ABATED
		. •	-	· ,
13/2	UNIT: 218 VSW FLOOR Floor covering, repair/replace KITCH		8. 2	
14/2	UNIT: 219 YSW FLOOR Door, hardware, repair/replace FRNT		8.4	
4.	NO ADMITTANCE GAINED TO THE FOLLOWING AREAS/UNITS:		en e	
	207		ļ· .	1-10
-	NO VIOLATIONS FOUND IN THE FOLLOWING AREAS/UNITS:  EXTERIOR AREAS  204  208  217  220  221  203  215  222		まる - 1 (8) t (8) で - 一般 (8)	18 (2) 18 (2) 18 (2) (300) 20 (47)
	CONTINUED PAGE 4			
	の過程機能は、結構では、1000円分割です。 の A Managage S の T D の で T D の で T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T D の T			75.7
		·		1 1 1
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE			
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDE	NROD		

State of Rew Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS BUREAU OF HOUSING INSPECTION

INSPECTION

PAGE NO.

0808-10569-0

APTS\* UNITS\*

TOTAL\*  $L(M) = \{ \mathbf{f} \in \mathcal{A}(\mathbf{f}) \mid \mathbf{f} \in \mathcal{A}(\mathbf{f}) : \mathbf{f} \in \mathcal{A}(\mathbf{f}) \}$ 

INSPECTOR\*

HARRISON, NJ 08098

 $v_i = \sum_{i=1}^{n} \zeta_i$ 

REGISTRATION NO.

VERDNICA S WOOD

MATE ISSUED

)ATE OF INSP.

09/20/2012

09/08/2012

DATE BY WHICH VIOLATIONS

NUST BE CORRECTED:

SS WOODSTOWN RD

MULLICA WEST LTD C/O BART

AXELROD

36 S MAIN ST

PLEASANTVILLE

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

BLDG. NO. 005

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

NE #	VIOLATIONS	CODE CITATION	REINSPECT O-OPEN VIC A-ABATE
P.S.P. MOTSTOON	F YOUR BUILDING WAS BUILT BEFORE 1978 AND IT IS NOT ERTIFIED AS BEING LEAD FREE ALL WORK PERFORMED TO ABATE AINTING VIOLATIONS OR VIOLATIONS THAT DISTURB PAINTED URFACES SHALL BE CARRIED OUT USING LEAD SAFE WORK RACTICES BY INDIVIDUALS TRAINED IN ACCORDANCE WITH J. A. C. 5:10-6.6(g). UPON RE-INSPECTION, THE PROPERTY WHER MUST HAVE AVAILABLE FOR THE INSPECTORS REVIEW ANY RAINING RECORDS TO SUPPORT COMPLIANCE WITH N. J. A. C. 10-6.6(g). AS WELL AS ANY REQUIRED WIPE SAMPLES SHOWING HE WORK AREA TO BE LEAD HAZARD FREE. IF THERE IS OCUMENTATION INDICATING THAT THE SURFACES CITED DO NOT ONTAIN LEAD BASED PAINT, THEN ALL WORK MUST COMPLY WITH J. A. C. 5:10-8.2.		To all the second of the secon
1	F YOU REQUIRE ADDITIONAL INFORMATION.  END VIOLATIONS		
	And the second of the second o	gydyd 14 y 1941 o 14 y 14	
	and the second of the second o	- 19 A	354 T
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

DATE OF INSP.

1.11

# INSPECTION

PAGE NO.

AREGISTRATION NO.

0808-10569-0

ORDERS OF THETYPE\*

UNITS\*

COMMISSIONER

TOTAL\* Country of the first stage of the country of

INSPECTOR\*

VERONICA S WOOD

SATE\_ISSUED \_\_\_O9/20/2012 DATE BY WHICH VIOLATIONS **4UST BE CORRECTED:** 

 $(a \otimes_i a) = (b \otimes_i a) = (a \otimes_i a) = (b \otimes$ 

\*\*BUILDING\*\* 0808

MULLICA WEST LTD C/O BART AXELROD
36 S MAIN ST.
PLEASANTVILLE NJ 08232

State of Mew Jersey DEPARTMENT OF COMMUNITY AFFAIRS ......

DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

08/08/2012

58 WOODSTOWN RD

HARRISON, NU 08098

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

OF 007 BLDGS.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S. 55:13A-1 et seq.).

LINE #	INSPECTION TYPE: VIOLATIONS	CODE CITATION	REINSPECTIO O-OPEN VIOL A-ABATED
1144 Pair	NOTE: IF ANY VIOLATIONS ARE PRECEDED BY A 'P', 'M' OR 'L', REFER TO THE FERMIT INFORMATION AT THE END OF THE REPORT.		
nger .	ALL CODE CITATIONS ARE PRECEDED BY 5:10, EXCEPT THOSE BEGINNING WITH THE NUMBER 4, WHICH ARE PRECEDED BY 5:70.		
**************************************	CODE CITATIONS BEGINNING WITH 6A OR 6B REFER TO APPENDICES 6-A AND 6-B OF N. J. A. C. S: 10-6. 6.	e giran e egilen egil	
1000 1000 1000 1000	ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C 5:70 ET SEG.		
1/2	EXTERIOR VSW LOCATION REPAIR LEADER TO DIRECT STORM WATER AWAY FROM BLDG. FOUNDATION WALLS.	7.5	45.0
2/2		8. 2	
3/2 4/2	· · · · · · · · · · · · · · · · · · ·		. 1 - 23 4
	CONTINUED PAGE 1 2	- 153	
-	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

MATE OF INSP.

State of New Jersey DEPARTMENT OF COMMUNITY AFFAIRS . DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

08/08/2012

# INSPECTION

PAGE NO.

REGISTRATION NO.

0809-10569-0

ORDERS OF THE TYPE\* MΩ

APTS\* **UNITS\*** 

TOTAL\*

INSPECTOR\* VERONICA S WOOD'

4 - 81 - 3 ( - 3

DATE ISSUED . 09/20/2012 )ATE BY WHICH VIOLATIONS **1UST BE CORRECTED:** 

TO ALEXANDER OF \*\*BUILDING\*\*

58 WOODSTOWN RD

HARRISON, NJ 08098

AXELROD 36 S MAIN ST .-

and materials of

MULLICA WEST LTD C/O BART

25280 LN

PLEASANTVILLE PROPERTY CONTACT PHONE NUMBER: 856-478-4422

007 BLDGS.

LONG THE STATE OF STREET

TAGE TO BEEL WAS THE TOWN TO STORE A

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

		<u> </u>	<u> </u>		*23 <sup>-4</sup>
LINE #	VIOLATIONS			CODE	REINSPECTIO O-OPEN VIOL A-ABATED
5/2	<u>UNIT:</u> 312 M REPAIR OR REPLACE ELECTRICAL SWITCH	<u>vsw</u>	<u>FLOOR</u> 1 DINING ROOM	(3, 1 (B)	
6/2 7/2	<u>UNIT:</u> 316 STORAGE REDUCE Storage move 3ft away of Heat equip	<u>лан</u>	<u>FLOOR</u> 1 HEATER ROOM HEATER ROOM	5. 8 6. 1	
e\5	<u>UNIT:</u> GOG S/D. REPLACE	<u>vsw</u>	FLOOR 2 HALL	4. 9	
7/2	<u>UNIT:</u> 311 Housekeeping, improve	<u>VSW</u>	FLOOR 2 APT UNIT	5. 4	
10/2	<u>UNIT:</u> G14 Stairways, exits, provide unrestri ge	<u>VSW</u> cted pass	FLOOR 2" a STAIRWAY	<b>6. 1</b>	<u> </u>
11/2	<u>UNIT:</u> 315 Rehab, continue, vacant unit	Aam	FLOOR 2	8. 2	
i2/2	<u>UNIT:</u> 319 Rehab, continue, vacant unit	<u>YSW</u>	FLOOR 2 APT UNIT	8. 2	
	CONTINUED PAGE 3				
	"ATTENTION" - FURTHER INSTRUCTION	NS ON REVER	SE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECT	TION COPY - PINK	AND GOLDENROD		

INSPECTION

REGISTRATION NO.

0608-10569-0

the second residual and the second

ORDERS OF THETYPE\*

MD

TOTAL\*

APTS\*

UNITS\*

INSPECTOR\* VERDNICA S WOOD

PAGE NO.

DATE ISSUED

PATE OF INSP.

09/20/2012

EXT PART OF THE PROPERTY.

08/08/2012

State of Rew Jersey DEPARTMENT OF COMMUNITY AFFAIRS

DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

DATE BY WHICH VIOLATIONS MUST BE CORRECTED:

TO BE THE THE WORLD TO A STATE A SEC \*\*BUILDING\*\*

MULLICA WEST LTD C/O BART

58 WOODSTOWN RD HARRISON, NJ 08078

AXELROD G6 S MAIN. ST. PLEASANTVILLE NJ 08232

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

organización de la composición de la c

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S. 55:13A-1 et seq.).

LINE #	VIOLATIONS		CODE	REINSPECTIO O-OPEN VIOL A-ABATED
		5 4×	·	
13/2	UNIT: 320	FLOOR 2 HALL	4. 🕫	
			e at the	
4 5 45	UNIT: 323 YAW	FLOOR 2		8 75 D LL
14/2 15/2	Housekeeping, improve	APT UNIT	5. 4	
16/2	Debris, bulk items, remove Storage area, eliminate	APT UNIT	6.1	<del>   </del>
17/2	S/D, REPLACE	HALL	6.1 4.9	
18/2	Stairways, exits, provide unrestricted passa		6.1	<del>   -</del>
	g≅	. —		
	NO ADMITTANCE GAINED TO THE FOLLOWING AREAS/ 321 302 322	UNITS:	e de la companya de l	
-				1 1 1
	NO VIOLATIONS FOUND IN THE FOLLOWING AREAS/ COMMON AREAS 304	UNITS:	> ·	-  -
	308 309	34 - 4 - g - 4		.
	313 317	•	,	
	324 306			
	307			
	<b>318</b>	24	12 .	
	CONTINUED PAGE 4		-1.5	
	e e		59	
	•			
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERS	E SIDE		
٠	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK A	AND GOLDENROD		

INSPECTION DEPARTMENT OF COMMUNITY AFFAIRS
DIVISION OF CODES AND STANDARDS

PAGE NO.

\*REGISTRATION NO.

0808-10569-0

ORDERS OF THE TYPE \* /MISSIONER

APTS\* **UNITS\*** 

TOTAL\* 24

INSPECTOR\*

to the second second VERONICA S WOOD

09/20/2012 . . . . . DATE ISSUED DATE BY WHICH VIOLATIONS **\*UST BE CORRECTED:** 

AXELROD

INSP.

11/19/2012

10 Sec. 253

\*\*BUILDING\*\*

ье морретоми ка HARRISON, NJ 08098

the garage of

36 S MAIN ST PLEASANTVILLE

State of Rew Jersey

**BUREAU OF HOUSING INSPECTION** 

08/08/2012

MULLICA WEST LTD C/O BART

ा खन्त्र ह क. NJ 08232

\*ROPERTY CONTACT PHONE NUMBER: 856-478-4422

BLDG. NO. 003

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	VIOLATIONS	CODE	REINSPECTION O-OPEN VIO
: :	'M' - A CONSTRUCTION PERMIT MAY DR MAY NOT BE REQUIRED CONTINGENT UPON THE EXTENT OF THE REQUIRED WORK TO ABATE THE CITED VIOLATION(S). COPIES OF THE ISSUED CONSTRUCTION OFFICIAL'S APPROVAL OF WORK COMPLETED MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE THE BUREAU OF HOUSING INSPECTION HAS COMPLETED IT'S	tury Newson tury Newson terror Stewn terror Stewn terror Stewn	* *, 5 P4
	REINSPECTION.	Andrew Services	
	CONTINUED PAGE 5	್. ಒಟ್ಟಿಕ್	
•			
	THE REPORT OF THE PROPERTY OF	7.75.7	
	THE COMPANY OF THE PROPERTY OF		
		1	1941 - 1 2 - 2 12 - 1 1 1
			1 34
: :	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE	• . •	
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

INSPECTION

REGISTRATION NO.

PAGE NO.

Y. . . . . . 3.

State of New Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

INSP.

08/08/2012

0808-10569

UNITS\*

INSPECTOR\* VERONICA S WOOD

.09/20/2012 JATE BY WHICH VIOLATIONS NUST BE CORRECTED:

建立。中 通 ##BUILDING##

MULLICA WEST LTD C/O BART 2 - 15

58 WOODSTOWN RD HARRISON, NJ 08098

Branch Bill of the San San San

AXELROD

GA B MAIN ST PLEASANTVILLE

NJ 08232

CONTACT PHONE NUMBER: 854-478-4422

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above . disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S. 55:13A-1 et seq.). 

CODE	REINSPECTION O-OPEN VIOL A-ABATED
	e e e Militar
	• •

)ATE OF INSP.

State of New Tersey **BUREAU OF HOUSING INSPECTION** 

DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS

08/08/2012

# INSPECTION

PAGE NO.

REGISTRATION NO:

ORDERS OF THETYPE\*

APTS\* UNITS# 24

Control of the second of the

OMMISSIONER

TOTAL\* 24

INSPECTOR\*

VERONICA S WOOD

)ATE ISSUED 09/20/2012 . )ATE BY WHICH VIOLATIONS

**WST BE CORRECTED:** 

11/19/2012

e garranti.

\*\*BUILDING\*\* 0808

MULLICA WEST LTD C/O BART

AXELROD

S8 WOODSTOWN RD HARRISON, NJ 08098

a ( , , ,

. . . .

36 S MAIN ST

PLEASANTVILLE

N1 08535

ROPERTY CONTACT PHONE NUMBER: 856-478-4422

. . .

BLDG. NO.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	INSPECTION TYPE: CYCLICAL VIOLATIONS	CODE CITATION	REINSPECTIO O-OPEN VIOL A-ABATED
ande.	NOTE: IF ANY VIOLATIONS ARE PRECEDED BY A 'P', 'M' OR "'L', REFER TO THE PERMIT INFORMATION AT THE END OF THE REPORT.	. "	ing. r
	ALL CODE CITATIONS ARE PRECEDED BY 5:10. EXCEPT THOSE BEGINNING WITH THE NUMBER 4. WHICH ARE PRECEDED BY 5:70.	r o e iste	
 	CODE CITATIONS BEGINNING WITH 6A OR 6B REFER TO APPENDICES 6-A AND 6-B OF N. J. A. C. 5: 10-6: 6.	2 ( ) ( ) ( ) ( )	
Touche South Touch	ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C 5:70 ET SEG.	2/ #	**************************************
1/2	EXTERIOR VSW LOCATION REPAIR LEADER TO DIRECT STORM WATER AWAY FROM BLDG. FOUNDATION WALLS.	7. 5	Negari
2/2		18. 2(A)	
3/2	UNIT: 408 Stove: Surners, repair KITCHEN	20.1(A)	
	CONTINUED PAGE 2		1 . 4: x 
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD	1	

INSPECTION

PAGE NO.

State of New Tersey DEPARTMENT OF COMMUNITY AFFAIRS: DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

09/08/2012

REGISTRATION NO.

0508-10567

ORDERS OF THETYPE\* **WISSIONER** 

APTS\* UNITS\* TOTAL\*

INSPECTOR\* VERDNICA S WOOD

MATE ISSUED 09/20/2012 NATE BY WHICH VIOLATIONS WET BE CORRECTED:

INSP.

日子記 しき ② \*\*BUILDING\*\*

MULLICA WEST LTD C/O BART AXELROD

58 WOODSTOWN RD HARRISON, NJ 08098

36 S MAIN ST PLEASANTVILLE

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 854-478-4422

BLDG.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A 55:13A-1 et seq.).

				DEINEDECTIO
LINE #	VIOLATIONS		CITATION	O-OPEN VIOL:
		<u> </u>		
		· · · · · · · · · · · · · · · · · · ·	, -	
	UNIT: 409	FLOOR 1		
4/2	Closet, repair/replace	HALL. HEATER ROOM	8. 2 (4. 3(E)	<del> </del>
5/2	PROVIDE HOT WATER HEATER PRESSURE RELIEF DISCHARGE PIPE WITHIN A MAXIMUM OF 20 INCHES		4.3(E)	
	FROM FLOOR.	in the second		
6/2		LIVING ROOM.	9.2	1 18
•	And the second of the second o	The state of the s		
New grown		<u>FLOOR</u> i		
7/2 8/2		APT UNIT	8.2	<del>  </del>
<b>⊕</b> / ≃	Door, hardware, repair/replace	nen-kii	8.4	<del>   </del>
	UNIT: 417	FLOOR 1		1 1 1
9/2	REPLACE OR REPAIR SMOKE DETECTOR.	HALL	4. 9	<u> </u>
Fig.		orenta Navigoro de la composición	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	UNIT: 424	FLOOR i	1.	-   Art.
10/2		BEDROOM 2	8.2	
11/2	Door, hardware, repair/replace	FRNT DOOR	8.4	<del> </del>
12/2		HALL	4. 9 8. 2	
13/2 14/2	CEILING, PAINT	HALL	8.2	<del>   </del>
15/2	Mitchen cabinents, repair/replace Stove, burners, repair	KITCHEN	20.1(A)	+
A hydr ham	wowyas bossessas commass	14 1 0 1 1 2 1 4	- No. 10	
	CONTINUED PAGE 3	1.60	7	1/4/91
		·	1	1 1
	And the state of t	• • • • • • • • • • • • • • • • • • • •		
		•		
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERS	ESIDE		1
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK A	ND COLDENDOD		
	OTTALE COFT - TABLE COFT - TELLOW REMOTECTION COFT - PINK A	IND GOLDENROD	1	1 1 1

INSPECTION

PAGE NO.

State of Rew Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS BUREAU OF HOUSING INSPECTION

DATE OF INSP.

08/08/2012

ORDERS OF THE TYPE\* OMMISSIONER

**APTS**\* UNITS\*

0808-10569-0

WINDLESS TOTAL\*

计图像 网络中国 医二十二氏性皮肤 电电流电流

VERONICA S WOOD INSPECTOR\*

ATT TO THE RESIDENCE

JATE ISSUED 09/20/2012 DATE BY WHICH VIOLATIONS AUST BE CORRECTED:

\*\*BUILDING\*\*

58 WOODSTOWN RD

HARRISON, NJ 08098

FREGISTRATION NO.

AXELROD TO MIAM 8 SE

**PLEASANTVILLE** 

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

MULLICA WEST LTD C/O BART

BLDG. NO. 004 OF 007 BLDGS.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

Control of the second

LINE #	VIOLATIONS	H PARTE TO S	CODE	REINSPECTIO O-OPEN VIOL A-ABATED
	Section 1995 and the section of the	1141 - 1 O 1 - 1 - 22	1,1	15 July 1
14/2	<u>UNIT:</u> 402 Floor covering, repair/replace	FLOOR 2 BATH	8.2	
17/2		<u>FLOOR</u> 2 STAIRWAY	7.6	
18/2	<u>UNIT:</u> 406 <u>YSW</u> M REPAIR BATH/TOILET ROOM VENTILATION EXHAUST	FLOOR 2 BATH	6.3	energia Langua digiligi se Light di a Totaligi
19/2	SYSTEM TO COMPLY WITH MIN REQ FOR THE EXHAUSTING OF SO CUBIC FT OF AIR/MINUTE. S/D, REPLACE	CHALL	<b>4. 9</b>	
20/2 21/2	UNIT: 410 VSW Door, hardware, repair/replace Handrail, 1.5 finger clearance provide 7.7		8.4 7.6	
55/5	<u>UNIT:</u> 415 Floor covering, trip hazard repair	FLOOR 2 KITCHEN	8.2	
E3/2	UNIT: 419 *** VSW Door, lock, hardware, repair/replace ****	FLOOR 2 FRNT DOOR	8. 4	
	CONTINUED PAGE 4	A Carlotte	9	*:
į	e de la companya de			
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSI	E SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK A	ND GOLDENROD		

#### State of Rew Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION**

DATE OF INSP.

INSPECTION

PAGE NO.

REGISTRATION NO.

0808-10569-0

APTS\* UNITS\*

INSPECTOR\* VERONICA S

09/20/2012, MATE ISSUED MATE BY WHICH VIOLATIONS **IUST BE CORRECTED:** 

SE WOODSTOWN RD

HARRISON, NJ 08098

AXELROD.

MULLICA WEST LTD C/O BART

36 S MAIN ST

PLEASANTVILLE CONTACT PHONE NUMBER: 854-478-4422

004 BLDG. NO.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance

with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A 55:13A-1 et seq.).

LINE #	VIOLATIONS	CODE	REINSPECTIO O-OPEN VIOL: A-ABATED
		1 44 = 5	2.1
	NO ADMITTANCE GAINED TO THE FOLLOWING AREAS/UNITS: 420 422 423	700000	
		OF 1	
	NO VIOLATIONS FOUND IN THE FOLLOWING AREAS/UNITS:		
· .	405 416 421 421 421 4 4 4 4 4 4 4 4 4 4 4 4 4 4	H .	
	407 414 418	at ·	,,
	'M' - A CONSTRUCTION PERMIT MAY OR MAY NOT BE REQUIRED CONTINGENT UPON THE EXTENT OF THE REQUIRED WORK TO ABATE THE CITED VIOLATION(S). COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE CONSTRUCTION OFFICIAL'S APPROVAL OF WORK COMPLETED MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE THE BUREAU OF HOUSING INSPECTION HAS COMPLETED IT'S REINSPECTION.		
	CONTINUED PAGE 5		
·			
3 .			
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

State of Rem Jersey DEPARTMENT OF COMMUNITY AFFAIRS **DIVISION OF CODES AND STANDARDS BUREAU OF HOUSING INSPECTION** 

JATE OF INSP. 08/08/2012

# INSPECTION

PAGE NO.

REGISTRATION NO.

0808-10569

APTS\* UNITS\*

INSPECTOR\*

ISSUED 09/20/2012 SATE BY WHICH VIOLATIONS AUST BE CORRECTED:

MAD MA \*\*BUILDING\*\*

4 (3) 35 - 36

58 WOODSTOWN RD

HARRISON, NJ 08098

AXELROD 36 S MAIN ST.

PLEASANTVILLE

NJ 08232

CONTACT PHONE NUMBER: 854-478-4422

MULLICA WEST LTD C/O BART

BLDG, NO. 904 OF 007

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

INE #	VIOLATIONS	CODE CITATION	REINSPECTION O-OPEN VIOLE A-ABATED
	IF YOUR BUILDING WAS BUILT BEFORE 1978-AND IT IS NOT CERTIFIED AS BEING LEAD FREE ALL WORK PERFORMED TO ABATE PAINTING VIOLATIONS OR VIOLATIONS THAT DISTURB PAINTED SURFACES SHALL BE CARRIED OUT USING LEAD SAFE WORK PRACTICES BY INDIVIDUALS TRAINED IN ACCORDANCE WITH N.J.A.C. 5:10-6.6(g). UPON RE-INSPECTION, THE PROPERTY OWNER MUST HAVE AVAILABLE FOR THE INSPECTORS REVIEW ANY TRAINING RECORDS TO SUPPORT COMPLIANCE WITH N.J.A.C. 5:10-6.6(g), AS WELL AS ANY REQUIRED WIPE SAMPLES SHOWING THE WORK AREA TO BE LEAD HAZARD FREE. IF THERE IS DOCUMENTATION INDICATING THAT THE SURFACES CITED DO NOT CONTAIN LEAD BASED PAINT, THEN ALL WORK MUST COMPLY WITH N.J.A.C. 5:10-8.2.		
.•	YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337 IF YOU REGUIRE ADDITIONAL INFORMATION.	1 ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) (	
 	YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337	374 	
 	YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337 IF YOU REGUIRE ADDITIONAL INFORMATION.	1949	
	YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337 IF YOU REGUIRE ADDITIONAL INFORMATION.		
	YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337 IF YOU REGUIRE ADDITIONAL INFORMATION.		
	YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337 IF YOU REGUIRE ADDITIONAL INFORMATION.		

DATE OF INSP.

# INSPECTION REPORT

PAGE NO.

.. CB. .. . 6

REGISTRATION NO.

0806-10569-0

State of Arm Jersey
DEPARTMENT OF COMMUNITY AFFAIRS
DIVISION OF CODES AND STANDARDS
BUREAU OF HOUSING INSPECTION

08/08/2012

AND

ORDERS OF THE TYPE\* MD

APTS\*
UNITS\*

INSPECTOR\* VERONICA S WOOD

DATE ISSUED 09/20/2012
DATE BY WHICH VIOLATIONS
HUST BE CORRECTED:

11/19/2012

WITCH DECK \*\*BUILDING\*\* OBOB

en gjaren

MULLICA WEST LTD C/O BART

58 WOODSTOWN RD

AXELROD

HARRISON, NJ 08098

36 S MAIN ST.

NJ 08232

PLEASANTVILLE

HV VUENE;

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

BLDG. NO. 005 OF 007 BLDGS

Broken Korist

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at sald premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.# 55:13A-1 et seq.).

LINE #	INSPECTION TYPE: CYCLICAL VIOLATIONS	CODE CITATION	REINSPECTIO O-OPEN VIOL A-ABATED
Marke Mager	NOTE: IF ANY VIOLATIONS ARE PRECEDED BY A 'P', 'M' OR 'L', REFER TO THE PERMIT INFORMATION AT THE END OF THE REPORT.		eters t
<del>-</del> ·	ALL CODE CITATIONS ARE PRECEDED BY 5:10. EXCEPT THOSE BEGINNING WITH THE NUMBER 4. WHICH ARE PRECEDED BY 5:70.		
	CODE CITATIONS BEGINNING WITH 6A OR 6B REFER TO APPENDICES 6-A AND 6-B OF N. J. A. C. 5: 10-6.6:		
	ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C 5:70 ET SEQ.		
1/2	EXTERIOR VSW LOCATION  REPAIR LEADER TO DIRECT STORM WATER AWAY, FROM BLDG  FOUNDATION WALLS.  Sidewalk/walk, repair, replace 506 510 516	7. 5 6. 4(A)	
3/2 4/2	UNIT: 501  M REPAIR BATH/TOILET ROOM VENTILATION EXHAUST BATH  SYSTEM TO COMPLY WITH MIN REQ FOR THE  EXHAUSTING OF SO CUBIC FT OF AIR/MINUTE.  Toilet, bath, shakes, secure  BATH	16. 3 21. 1(A)	
	CONTINUED PAGE 2		
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

HATE OF INSP.

State of New Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

08/08/2012

### INSPECTION REPORT

PAGE NO.

0808-10569-0

2

ORDERS OF THE TYPE \*

APTS\* UNITS\*

OMMISSIONER

TOTAL\*

INSPECTOR\*  $1 + (1.176 \pm 0.05)$ 

Contract Contract

REGISTRATION NO.

VERONICA S WOOD

PATE ISSUED 09/20/2012 )ATE BY WHICH VIOLATIONS

WET BE CORRECTED: 11/19/2012

\*\*BUILDING\*\* 0808

MULLICA WEST LTD C/O BART , i ;

58 WOODSTOWN RD

AXELROD

HARRISON, NJ ÖB098

36 S MAIN ST

그런걸요...댓글: (24 1...)

PLEASANTVILLE

NJ 08232

ROPERTY CONTACT PHONE NUMBER: 856-478-4422

007 BLDGS.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

The state of the

LINE #	VIOLATIONS	CODE	REINSPECTIO O-OPEN VIOL A-ABATED
	UNIT: 504 YSW FLOOR 1		
5/2 6/2	Storage move 3ft away of Heat equip. HEATER ROOM HEATER ROOM	5. 8	
7/2 8/2	Floor covering, repair/replace KITCHEN	8. 2 8. 2	
<b>4/2</b>	UNIT: 513 YSW FLOOR 1 M REPAIR BATH/TOILET ROOM VENTILATION EXHAUST BATH SYSTEM TO COMPLY WITH MIN REG FOR THE EXHAUSTING OF SO CUBIC FT OF AIR/MINUTE.	6.3 Dag	
10/2	CAULK/GROUT BATHTUB AREA BATH  VSW FLOOR 1	21.1(A)	14.
11/2 12/2 13/2 14/2	CEILING/WALL PAINT BATH REPLACE OR REPAIR SMOKE DETECTOR. HALL STORAGE REDUCE HEATER ROOM Storage move 3ft away of Heat equip. HEATER ROOM	8. 2 4. 7 5. 8 6. 1	
15/2 16/2	UNIT: 524  Floor/ threshold plate, repair/replace  FRNT DOOR  REPLACE OR REPAIR SMOKE DETECTOR.  HALL	8. 2 4. 9	a rajęci
	CONTINUED PAGE 3	V -:	
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

State of Rem Tersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS

**BUREAU OF HOUSING INSPECTION** 

08/08/2012

MULLICA WEST LTD C/O BART

INSPECTION

REGISTRATION NO.

0808-10569-0

ORDERS OF THETYPE\* COMMISSIONER

APTS\* UNITS\*

TOTAL\*

. 24

INSPECTOR\* VERONICA S WOOD

PAGE NO.

DATE ISSUED 09/20/2012 DATE BY WHICH VIOLATIONS **1UST BE CORRECTED:** 

INSF.

. 21.

いえがいがら、to \*\*BUILDING\*\* 9090

59 WOODSTOWN RD

HARRISON, NJ 08098

AXELROD

36 S MAIN ST PLEASANTVILLE

NJ 08232

ROPERTY CONTACT PHONE NUMBER: 056-478-4422

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.# 55:13A-1 et seq.). 

LINE #	VIOLATIONS	The second secon	CODE CITATION	REINSPECTIO O-OPEN VIOL A-ABATED
			र्गर कर पुरावक्रम	tan Kal
17/2	<u>UNIT:</u> 502 L PAINT ENTIRE DWELLING UNIT:	FLOOR 2 APT UNIT	8.2(C)	
	<u>UNIT:</u> 511	FLOOR 2	1-1-1-13 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1	20 - 20 - 20 - 20 - 20 - 20 - 20 - 20 -
	Rehab, continue, vacant unit	APT UNIT	8. 2	baz r o
19/2	UNIT: S14	FLOOR 2	5.5	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1
	L PAINT ENTIRE DWELLING UNIT.		8.2(C)	
21/2	KITCHEN, CABINETS, REPAIR/REPLACE	KITCHEN	8.2	
55/5	Refrigerator, leak, repair	KITCHEN :	20.1(A)	
23/2 24/2	UNIT: 519 Housekeeping, improve MAINTAIN PLUMBING FIXTURES IN CLEAN AND SANITARY CONDITION	FLOOR 2 APT UNIT BATH	5. 4 5. 4	40 cm, 34 se
* 2 · 10	UNIT: 522  Floor covering, repair/replace  Toilet, flush mechanism, repair	FLOOR 2		7.05
25/2 26/2	Floor covering, repair/replace	APT UNIT	8. 2	<del></del>
27/2			21.1(A) 20.1(A)	<del> </del>
28/2	REPAIR OR REPLACE FAUCET.		21.1(E)	
	CONTINUED PAGE 4	the state of the second	3	
	to the state of th	er est ou en la company de		
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE	SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AI	ND GOLDENROD		

State of Rem Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

DATE OF INSP. 09/08/2012

# INSPECTION

PAGE NO.

REGISTRATION NO.

0808-10569-C

**ORDERS OF THE TYPE\*** MD e e garangan yan sa APTS\* UNITS\*

· TOTAL\*

INSPECTOR\* VERONICA Š WOOD

DATE ISSUED 09/20/2012 DATE BY WHICH VIOLATIONS NUST BE CORRECTED:

\*\*BUILDING\*\*

58 WOODSTOWN RD

HARRISON, NJ 08098

AXELROD 36 S MAIN ST

 $(X^{n,n} \otimes P_{n,n}) = (g_n \otimes \underline{Z} \otimes_{\underline{Z}} \otimes \dots \otimes_{\underline{Z}} \otimes P_{n,n}) = (g_n \otimes \underline{Z} \otimes_{\underline{Z}} \otimes \dots \otimes_{\underline{Z}} \otimes P_{n,n})$ 

PLEASANTVILLE

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

MULLICA WEST LTD C/O BART

BLDG. NO.

and the said 100

Sold to be about the man per "

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	VIOLATIONS	CODE CITATION	REINSPECTION O-OPEN VIO A-ABATEI
		T 2 4,5 36	
	NO ADMITTANCE GAINED TO THE FOLLOWING AREAS/UNITS: 521 518	. 4 ; 14 4 <b>. 4</b> . 4 .	요 된
	NO VIOLATIONS FOUND IN THE FOLLOWING AREAS/UNITS:	80 TO	5.00
	COMMON AREAS 509 609 609 609 609 609 609 609 609 609 6	Angle Aghi Salah Lini Lini Angle Aghi Salah B	en e
	'M' - A CONSTRUCTION PERMIT MAY OR MAY NOT BE REQUIRED CONTINGENT UPON THE EXTENT OF THE REQUIRED WORK TO ABATE THE. CITED VIOLATION(S). COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE CONSTRUCTION OFFICIAL'S APPROVAL OF WORK COMPLETED MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE THE BUREAU OF HOUSING INSPECTION HAS COMPLETED IT'S REINSPECTION.		10 taq.
	CONTINUED PAGE 5	e de la companya de l	i de la companya di salah di s
	in the second of		
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	ATTENTION - FORTHER INSTRUCTIONS ON REVERSE SIDE	į.	1 1

## INSPECTION

PAGE NO.

State of Rem Tersep DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

0808-10569-0

· MATE OF INSP. 08/08/2012

· UNITS\*

VERONICA S WOOD

substitution of the property of

PATE ISSUED .09/20/2012 DATE BY WHICH VIOLATIONS TUST BE CORRECTED:

Differ Build of Fighter Her Stand Duffer \*\*BUILDING\*\*

MULLICA WEST LTD C/O BART

58 WOODSTOWN RD

INSPECTOR\*

REGISTRATION NO.

AXELROD

HARRISON, NJ. 08099. Assert State of the State of th 

36 S MAIN STON PLEASANTVILLE

NJ 08232

'ROPERTY CONTACT PHONE NUMBER: 856-478-4422

BLDG. NO.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S. 55:13A-1 et seq.).

LINE #	VIOLATIONS	CODE CITATION	REINSPECTION O-OPEN VIOLA-ABATED
. g.w.	'L' — A CONSTRUCTION PERMIT MAY OR MAY NOT BE REQUIRED CONTINGENT UPON THE EXTENT OF THE REQUIRED WORK TO CORRECT THE CITED VIOLATION(8). IN THE EVENT THAT THE VIOLATIONS ARE TO BE CORRECTED THROUGH LEAD ABATEMENT FURSUANT TO N. J. A. C. S: 17. A CERTIFIED LEAD ABATEMENT CONTRACTOR IS REQUIRED AND A CONSTRUCTION PERMIT MUST BE OBTAINED. COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE CONSTRUCTION OFFICIAL'S APPROVAL OF WORK MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE BUREAU OF HOUSING INSPECTION HAS COMPLETED ITS REINSPECTION. DOCUMENTATION FOR WORK PERFORMED BY A CERTIFIED LEAD ABATEMENT CONTRACTOR MUST BE MADE AVAILABLE TO THE BUREAU UPON REQUEST.		
	CONTINUED PAGE 6	en e	48 - 19 1 30 T 1 1 1 1 1 1
:			
			3 23 3 3 3 4 3 48 7
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

State of Dew Jersey
DEPARTMENT OF COMMUNITY AFFAIRS
DIVISION OF CODES AND STANDARDS
BUREAU OF HOUSING INSPECTION

MATE OF INSP. 08/08/2012

# INSPECTION REPORT

PAGE NO.

REGISTRATION NO.

0908-10569-0

AND

ORDERS OF THE TYPE\* MD

APTS\* UNITS\* .TOTAL\*

24

1 ...

COMMISSICIATION

INSPECTOR\* (

VERONICA S' WOOD

DATE ISSUED 09/20/2012 DATE BY WHICH VIOLATIONS SUST BE CORRECTED:

11/19/2012 :/a. \angle 
MULLICA WEST LTD C/D BART

.58 WOODSTOWN RD .HARRISON, NJ 08098

and an income the second

AXELROD

36 S MAIN ST. X PLEASANTVILLE

NJ 08232

ROPERTY CONTACT PHONE NUMBER: 856-478-4422

record to the resolution

BLDG, NO. 005 OF 007 BLDGS

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	VIOLATIONS	CODE	REINSPECTION O-OPEN VIOLA-ABATED
	IF YOUR BUILDING WAS BUILT BEFORE 1978 AND IT IS NOT	e projek en la	
	CERTIFIED AS BEING LEAD FREE ALL WORK PERFORMED TO ABATE PAINTING VIOLATIONS OR VIOLATIONS THAT DISTURB PAINTED SURFACES SHALL BE CARRIED OUT USING LEAD SAFE WORK PRACTICES BY INDIVIDUALS TRAINED IN ACCORDANCE WITH	1.7 1.8 1.7	.2.7
	N. J. A. C. 5:10-6.6(g). UPON, RE-INSPECTION, THE PROPERTY DWNER MUST HAVE AVAILABLE FOR THE INSPECTORS REVIEW ANY TRAINING RECORDS TO SUPPORT COMPLIANCE WITH N.J. A. C. 5:10-6.6(g), AS WELL AS ANY REQUIRED WIPE SAMPLES SHOWING		
	THE WORK AREA TO BE LEAD HAZARD FREE. IF THERE IS DOCUMENTATION INDICATING THAT THE SURFACES CITED DO NOT CONTAIN LEAD BASED PAINT, THEN ALL WORK MUST COMPLY WITH N. J. A. C. S: 10-8. 2.		£
**	YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2397 IF YOU REQUIRE ADDITIONAL INFORMATION.		a s a gran
.	END VIOLATIONS		
·•		14 14 14 14 14 14 14 14 14 14 14 14 14 1	r gar
Ì			
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
, !	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

# INSPECTION

PAGE NO.

REGISTRATION NO.

0808-10569-C

State of Rew Tersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

INSP. 08/08/2012

ORDERS OF THE TYPE\*

Them -

UNITS\* TOTAL\*

INSPECTOR\* VERONICA S WOOD

PATE ISSUED 09/20/2012 DATE BY WHICH VIGLATIONS **WET BE CORRECTED:** 

AXELROD

11/19/2012 

\*\*BUILDING\*\*

APTS\*

58 WOODSTOWN RD

HARRISON, NJ 08098

MD

医二生乳糖 医乳头炎

GA S MAIN ST PLEASANTVILLE

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

The Contract of the State of the

MULLICA WEST LTD C/O BART

THE JUST NEWSCOOL STORY

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	INSPECTION TYPE: CYCLICAL VIOLATIONS	CODE	REINSPECTIO O-OPEN VIOL A-ABATED
terr	NOTE: IF ANY VIOLATIONS ARE PRECEDED BY A 'P', 'M' OR 'L', REFER TO THE PERMIT INFORMATION AT THE END OF THE REPORT.	្រ ខ្លាំ	g i
eer Nyd? ee	ALL CODE CITATIONS ARE PRECEDED BY 5:10/ EXCEPT THOSE BEGINNING WITH THE NUMBER 4. WHICH ARE PRECEDED BY 5:70.		TO THE STATE OF TH
	CODE CITATIONS BEGINNING WITH 6A OR 6B REFER TO APPENDICES 6-A AND 6-B OF N. J. A. C. 5: 10-6. 6.		
enen 1 sz. z penen penen	ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C 5:70 ET SEG.	1 projection (1984)	
1/2	UNIT: 601 VSW LOCATION M REPAIR OR REPLACE WASH BASIN IN BATHROOM. BATH	21.1(A)	
3\5 5\5	UNIT: 604 STORAGE REDUCE Storage move 3ft away of Heat equip. HEATER ROOM	5. 8 6. 1	
4/2 5/2	UNIT: 612 <u>VSW</u> <u>FLOOR</u> 1 Tub, reglaze BATH Basin, bathroom, faucet repair/replace BATH	21.1(A) 21.1(A)	
	CONTINUED PAGE 2		Control of
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
٠.	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

State of New Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

DATE OF INSP. 08/08/2012 INSPECTION

PAGE NO.

REGISTRATION NO.

0808-10569

MD

UNITS\*

TOTAL\*

INSPECTOR\*

)ATE ISSUED

09/20/2012

DATE BY WHICH VIOLATIONS

**NUST BE CORRECTED:** 

4-5000 8-4000

ALLE TO SEE \*\*BUILDING\*\*

MULLICA WEST LTD C/O BART

AXELROD .

.58 WOODSTOWN RD HARRISON, NJ 08098

36 S MAIN ST

NJ 08232

PLEASANTVILLE

'ROPERTY CONTACT PHONE NUMBER: 856-478-4422

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE #	VIOLATIONS		CODE CITATION	REINSPECTIO O-OPEN VIOL A-ABATED
6/2	Refrigerator, repair/replace	KITCHEN :	20.1(A)	18. 19. 64
7/2	Stove, repair/replace		20.1(A)	
	WEV : CIA: TINU	FLOOR 1	:	
8/2	Tub. reglaze	BATH	21.1(A)	
9/2	Refrigerator, repair/replace	KITCHEN	20. 1(A)	
10/2	Refrigerator, defective parts, repair		20.1(A)	
	UNIT: 617	FLOOR 1		1.0
11/2			20. 1(A)	<del>  </del>
	<u>UNIT:</u> 620	FLOOR 1	- '}	
12/2	· · · · · · · · · · · · · · · · · · ·	APT UNIT	5. 4	<del>  </del>
13/2	REMOVE ILLEGAL EXTENSION CORDS.	APT UNIT	(3.1(D)	<del> </del>
14/2	UNIT: 624 VSW DOOR, REPAIR/REPLACE	FLOOR. 1		
15/2		BED 182	8. 4	<del>   </del>
16/2	STORAGE REDUCE Storage move 3ft away of Heat equip.	HEATER ROOM HEATER ROOM	5.8	<del>   </del> -
17/2		HEATER ROOM	6.1	<del>  </del>
٤//حد	Door, repair	HEATER ROUM	8. 4	<del>   </del> -
	UNIT: 607	FLOOR 2		
18/2		BATH.	5. 5	
17/2	lub, regiaze	BATH.	21.1(A)	
		* 1.7		1 1 1
	CONTINUED PAGE: 18	i e e	-	
				`
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE	E SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK A	ND GOLDENROD	].	1 1

State of Rew Jersey DEPARTMENT OF COMMUNITY AFFAIRS .... DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

# INSPECTION

REGISTRATION NO.

0805-10569-0

ORDERS OF THE TYPE \*

APTS# UNITS\*

Park that the first of the parket

and the contract of the contra

MISSIONER

TOTAL\* 24 រួមទេ២ អាទមានដូលមា រូបប៉ះប្រាស់

INSPECTOR\*

VERONICA S WOOD "

DATE ISSUED 09/20/2012 PATE BY WHICH VIOLATIONS

**YUST BE CORRECTED:** 

MULLICA WEST LTD C/O BART

AXELROD

58 WOODSTOWN RD

36,8 MAIN ST

HARRISON, NJ 08098 क्राक्रम (क्राप्तिकी

PLEASANTVILLE

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

growing the grade of the con-007

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Fallure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.k. 55:13A-1 et seq.).

Compared to the second of the second

LINE	VIOLATIONS	Conservation (Conservation Conservation Cons	CODE	REINSPECTIO
#,	VIOLATIONS	e e e e e e e e e e e e e e e e e e e	CITATION	O-OPEN VIOL: A-ABATED
50/5	Shower, wall repair/replace	BATH.	21.1(A)	7 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
21/2		<u>SW</u> <u>FLOOR</u> 2 BATH	2i, i.(A)∷.∈	
	NO ADMITTANCE GAINED TO THE FOLLOWIN 610	G AREAS/UNITS:	६ - इक्ष्माच्या स्ट्री १ र २ १ व्या १५ ४	\$ 1 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	NO VIOLATIONS FOUND IN THE FOLLOWIN			a version station in the disease
* 3	EXTERIOR AREAS COMMON A 605 608 607 616 603			e was the first of
* + *	611 614 615 618 619 622	機能を通過 では、これを、これがある。 R.D. Part Control of The August Control Control of The Control of	Salando esta Bultilentula Etilopolia	15. (2) [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ]
	'M' - A CONSTRUCTION PERMIT MAY OR M CONTINGENT UPON THE EXTENT OF THE REQ THE CITED VIOLATION(S). COPIES CONSTRUCTION PERMITS AND THE CONST	UIRED WORK TO ABATE OF THE ISSUED RUCTION OFFICIAL'S		
";	APPROVAL OF WORK COMPLETED MUST BE PR IN THE IMMEDIATE VICINITY OF THE WORK THE BUREAU OF HOUSING INSPECTION REINSPECTION.	PERFORMED UNTIL THE	14	
	CONTINUED PAGE 4	en e		1 10 1 200 - 1
;	"ATTENTION" - FURTHER INSTRUCTIONS C	ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION	COPY - PINK AND GOLDENROD		

1 - 21 - 4



INSPECTION

PAGE NO.

- REGISTRATION NO.

0808-10569-0

ORDERS OF THE TYPE \*

APTS\* UNITS\*

COMMISSIONER

TOTAL\* 24 

INSPECTOR\* VERONICA S WOOD

DATE ISSUED . 09/20/2012 DATE BY WHICH VIOLATIONS WIST BE CORRECTED:

INSP.

11/19/2012

Wast Street Bearing \*\*BUILDING\*\*

. SO WOODSTOWN RD

And the state of the state of

HARRISON NJ 08098

MULLICA WEST LTD C/O BART MULLICA WEST LID AXELROD AXELROD AXELROD AXELROD

08/08/2012

PLEASANTVILLE NJ 08232

\*ROPERTY CONTACT PHONE NUMBER: 856-478-4422 BLDG. NO.

006 OF 007

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seg.). and the second s

LINE #	VIOLATIONS	CODE CITATION	REINSPECTION O-OPEN VIO
	IF YOUR BUILDING WAS BUILT BEFORE 1978 AND IT IS NOT CERTIFIED AS BEING LEAD FREE ALL WORK PERFORMED TO ABATE PAINTING VIOLATIONS OR VIOLATIONS THAT DISTURB PAINTED SURFACES SHALL BE CARRIED OUT USING LEAD SAFE WORK PRACTICES BY INDIVIDUALS TRAINED IN ACCORDANCE WITH N.J.A.C. 5:10-6.6(g). UPON RE-INSPECTION, THE PROPERTY OWNER MUST HAVE AVAILABLE FOR THE INSPECTORS REVIEW ANY TRAINING RECORDS TO SUPPORT COMPLIANCE WITH N.J.A.C. 5:10-6.6(g). AS WELL AS ANY REGUIRED WIPE SAMPLES SHOWING THE WORK AREA TO BE LEAD HAZARD FREE. IF THERE IS DOCUMENTATION INDICATING THAT THE SURFACES CITED DO NOT CONTAIN LEAD BASED PAINT, THEN ALL WORK MUST COMPLY WITH N.J.A.C. 5:10-8.2.  YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337. IF YOU REQUIRE ADDITIONAL INFORMATION.		
· · · · · · · · · · · · · · · · · · ·	END VIOLATIONS TO THE TAXABLE TO THE		
·	en de la companya de La companya de la co La companya de la companya del companya del companya de la companya del companya de la companya del companya de la companya de la companya de la companya de la companya del company	。 (2) (2) (2) (4) (4) (4)	3
-	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

JATE OF INSP.

State of New Jersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

## INSPECTION

PAGE NO.

REGISTRATION NO.

ORDERS OF THE TYPE\*

APTS\* UNITS\*

COMMISSIONER

TOTAL\*

INSPECTOR\* VERUNICA S WOOD

DATE ISSUED 09/20/2012 DATE BY WHICH VIOLATIONS YUST BE CORRECTED:

11/19/2012

BOBO \*\*BUILDING\*\* 0808

MAC \$3, 15 MULLICA WEST LTD C/D BART

S8 WOODSTOWN RD

HARRISON, NJ 08098

AXELROD

FLEASANTVILLE NU 08232

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Fallure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S. 55:13A-1 et seg.).

LINE #	INSPECTION TYPE: VIOLATIONS	CODE CITATION	REINSPECTIO O-OPEN VIOL A-ABATED
	NOTE: IF ANY VIOLATIONS ARE PRECEDED BY A 'P'; 'M' OR 'L'; REFER TO THE PERMIT INFORMATION AT THE END OF THE REPORT.	e jako	
tene .	ALL CODE CITATIONS ARE PRECEDED BY 5:10, EXCEPT THOSE BEGINNING WITH THE NUMBER 4, WHICH ARE PRECEDED BY 5:70.	- 10 AP	6-11 0 - 12 - 122 - 13 - 123
	CODE CITATIONS SEGINNING WITH 6A OR 6B REFER TO APPENDICES 6-A AND 6-B OF N. J. A. C. 5: 10-6. 6.	· · · · · · · · · · · · · · · · · · ·	
terio , , , , , , , , ,	ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C 5:70 ET SEQ.		1 01 7 7 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1/2	EXTERIOR VSW LOCATION Sidewalk/walk, repair, replace 703	6.4(A)	The second secon
2/2	UNIT: 704 VSW FLOOR i	21.1(A)	
3/2	UNIT: 705 Floor, threshold plate, repair/replace FRNT DOOR CONTINUED PAGE 2	8. 2	, ngapa ti Nasa L
;	agent to the second of the sec		6 , F
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

INSPECTION

PAGE NO.

0808-10569-0

State of Mew Tersey DEPARTMENT OF COMMUNITY AFFAIRS DIVISION OF CODES AND STANDARDS **BUREAU OF HOUSING INSPECTION** 

08/08/2012

ORDERS OF THE TYPE \* MISSIONER

APTS\*

UNITS\* TOTAL\*:..

INSPECTOR\*

REGISTRATION NO.

Continue or the end of the con-VERONICA S'WOOD

PATE 166UED 07/20/2012 MATE BY WHICH VIOLATIONS TUST BE CORRECTED:

11/19/2012

THE TRANSPORT \*\*BUILDING\*\* 0808

er i de sant general de sant Propinsion de sant general de

58 WOODSTOWN RD

HARRISON, NJ 08098

AXELROD 36 S MAIN ST

NA 08535

\*:-

PLEASANTVILLE PROPERTY CONTACT PHONE NUMBER: 856-478-4422

MULLICA WEST LTD C/Q BART

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

the transfer of the contract o

LINE	The second secon	CODE	REINSPECTIO
#	VIOLATIONS	CITATION	O-OPEN VIOL A-ABATED
		100	-::::::::::::::::::::::::::::::::::::::
4/2 5/2		8. 2 8. 2	
6/2 7/2		8. 2 8. 2(C)	2000 2000 2000 2000 2000 2000 2000
8/2	UNIT: 717 VSW FLOOR 1 REMOVE ILLEGAL EXTENSION CORDS. HEATER ROOM	ເສ. 1 (D),	
7/2 10/2	UNIT: 724  Ceiling, wall, locate source of leak, repair BATH CEILING, PAINT  BATH.	8. 2 8. 2	
•	NO ADMITTANCE GAINED TO THE FOLLOWING AREAS/UNITS: 703 704 714 718	20 3	
	NO VIOLATIONS FOUND IN THE FOLLOWING AREAS/UNITS: COMMON AREAS 701 708 709 712 720		7 d : - f
	CONTINUED PAGE 3		
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

HATE OF INSP.

State of New Jersey DEPARTMENT OF COMMUNITY AFFAIRS... **DIVISION OF CODES AND STANDARDS BUREAU OF HOUSING INSPECTION** 

08/08/2012

that have been a will be a

INSPECTION REPORT

PAGE NO.

- REGISTRATION NO.

0808-10569-0

ORDERS OF THE TYPE\*

APTS\* UNITS\* TOTAL \*

COMMISSIONER

11 12 75

INSPECTOR\*

VERONICA S WOOD

DATE JESUED \_\_\_ 09/20/2012 DATE BY WHICH VIOLATIONS 1UST BE CORRECTED;

11/19/2012

- TANALALAS ( MAIN MAIN AND MAIN A\*BUILDING\*\* 0808

בא אססמבּדָסאא אם

HARRISON, NJ 08098 HARRISON, NJ 08098

MULLICA WEST LTD C/O BART AXELROD 36 S MAIN. ST

PLEASANTVILLE NJ 08232

हर राज्या का अन्य क्रिकार के क

PROPERTY CONTACT PHONE NUMBER: 855-478-4422 BLDG. NO. 007 OF 007 BLDGS.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.),

LINE #	VIOLATIONS	CODE	REINSPECTIO O-OPEN VIOL A-ABATED
	NO VIOLATIONS FOUND IN THE FOLLOWING AREAS/UNITS: 721 702 707 710 715		ersen de la
	722  723  724  725  726  727  727  728  729  729  720  720  720  720  720  720		を (本)
	CONTINUED PAGE 4		2 - 2 - 4 2 - 2 2 - 2 2 - 2 2 - 3 2 - 3 3 - 3 3 - 3
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		

1 11 10111



# INSPECTION

PAGE NO.

REGISTRATION NO.

0808-10569-C

ORDERS OF THE TYPE\*

APTS\* UNITS\*

TOTAL\* 

VERONICA S WOOD

MATE ISSUED 09/20/2012

08/08/2012

JATE BY WHICH VIOLATIONS AUST BE CORRECTED:

- 1: :::: \*\*BUILDING\*\*

58 WOODSTOWN RD

INSPECTOR\*

MULLICA WEST LTD C/O BART

AXELROD

11/19/2012

36 S MAIN ST PLEASANTVILLE

NJ 08232

PROPERTY CONTACT PHONE NUMBER: 856-478-4422

who is the property attacks

007, OF 007 BLDGS.

Please take notice that the inspection conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that the violations listed below exist at said premises in contravention of the Hotel & Multiple Dwelling Law and the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated thereunder. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and the Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76), as amended and supplemented (N.J.S.A. 55:13A-1 et seq.).

LINE	VIOLATIONS	CODE CITATION	REINSPECTIO O-OPEN VIOL
# .	The state of the s	CHAHON	A-ABATED
	IF YOUR BUILDING WAS BUILT BEFORE 1978 AND IT IS NOT CERTIFIED AS BEING LEAD FREE ALL WORK PERFORMED TO ABATE PAINTING VIOLATIONS OR VIOLATIONS THAT DISTURB PAINTED SURFACES SHALL BE CARRIED OUT USING LEAD SAFE WORK PRACTICES BY INDIVIDUALS TRAINED IN ACCORDANCE WITH N.J.A.C 5:10-4.6(q). UPON RE-INSPECTION, THE PROPERTY OWNER MUST HAVE AVAILABLE FOR THE INSPECTORS REVIEW ANY TRAINING RECORDS TO SUPPORT COMPLIANCE WITH N.J.A.C. 5:10-6.6(q). AS WELL AS ANY REQUIRED WIPE SAMPLES SHOWING THE WORK AREA TO BE LEAD HAZARD FREE, IF THERE IS DOCUMENTATION INDICATING THAT THE SURFACES CITED DO NOT CONTAIN LEAD BASED PAINT, THEN ALL WORK MUST COMPLY WITH N.J.A.C. 5:10-8.2.		
	YOU MAY CONTACT THE BUREAU'S LEAD UNIT AT (609) 777-2337 IF YOU REQUIRE ADDITIONAL INFORMATION.	148 (4.5) 14 (4.5) 15 (4.5)	erak Maria Serak Jelongko
٠. ٠	END VIOLATIONS TO THE PROPERTY OF THE PROPERTY		t T
	And the second of the second o		yr ()   1277   1374
		ų šeri	
	"ATTENTION" - FURTHER INSTRUCTIONS ON REVERSE SIDE		
	OWNER COPY - WHITE FILE COPY - YELLOW REINSPECTION COPY - PINK AND GOLDENROD		



#### Capital Needs Assessment Executive Summary



Project: Mullica West Apartments

Date: NEW CONSTRUC

		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	
Item	H&S	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	Total
Site	0	1736019	0	C	0	0	0	0	0	0	0	0	0	20000	0	0	135000	0	0	0	0	\$1,891,019
Architecture	0	1139000	0	C	0	0	0	0	0	0	0	8400	0	0	0	0	33600	0	0	0	0	\$1,181,000
Mech & Electric	0	1685040	0	0	0	0	0	0	0	0	0	126000	0	0	0	0	0	0	0	0	411600	\$2,222,640
Dwelling Units	0	3676148	0	0	0	0	0	0	76006	54600	0	0	0	0	0	394912	422066	54600	0	0	84000	\$4,762,332
Uninflated Totals	0	8,236,207	0	0	0	0	0	0	76,006	54,600	0	134,400	0	20,000	0	394,912	590,666	54,600	0	0	495,600	\$10,056,991
Inflation Factor (3%)	1.0000	1.0000	1.0300	1.0609	1.0927	1.1255	1.1593	1.1941	1.2299	1.2668	1.3048	1.3439	1.3842	1.4258	1.4685	1.5126	1.5580	1.6047	1.6528	1.7024	1.7535	
Inflated Totals	0	8,236,207	0	0	0	0	0	0	93,478	69,166	0	180,622	0	28,515	0	597,340	920,238	87,617	0	0	869,038	\$11,082,221

			Non-Inflated	Inflated
		Immediate Capital Needs:	\$0	
		Total Capital Needs Over the Term:	\$10,056,991	\$11,082,221
		Grand Total Capital Needs:	\$10,056,991	\$11,082,221
Units:	168	Capital Needs Per Unit	\$59,863	\$65,966

### Capital Needs Assessment Materials and Conditions - Site



### Capital Needs Assessment Capital Needs Over the Term - Site

USDA Rural Developmen

**Project: Mullica West Apartments** Date: 7/22/2013 **Project: Mullica West Apartments** Date: NEW CONSTRUCTION Unit 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 Total 1 2 3 Action DUR QTY Cond Unit Cost Cost Comments H&S 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 Total Existing Parking 15 15 Good Repair 135,000 135000 New top coat 135000 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 270000 Existing Parking Re-striping 40000 12 Good Repair 20000 20000 Re-striping 116400 Handicapped access to units Curbs & walks Curbs & walks 30 Good Repair 116400 116400 Landscaping Site Lighting 50 Good 1 ea 400000 400000 400000 Maintain Landscaping 30 Good Construct 75 poles 7500 562500 Site Lighting 562500 Handicapped curb cuts 30 500 4000 4000 30 Good Replace 4000 Handicapped curb cuts New underground piping 2915 20405 system 20405 Downspout piping 20 Good Repair Downspout piping Re-build maintenance bldg
Plumbing/ site sanitary 40 40 Good 2520 sf 35 88200 New building 88200 88200 Replace Re-build maintenance bldg Plumbing/ site sanitary system clean out lines (7 system clean out lines (7 20 Good 2500 17500 17500 17500 bldgs) Repair bldgs) New Road & Parking 25 25 Good Construct 7633 sy 12 91596 New Road & Parking 91596 91596 25 25 Good 3880 sy Existing Road 34920 New 2" overlay Existing Road 34920 34920 Construct Demolition 25 Good 50000 50000 50000 50000 Replace Demolition Curb 30 30 Good Construct 0 5857 lf 14 81998 Belgium Block Curb 81998 81998 0 Offsite Sidewalk 25 25 Good 12250 sf 73500 73500 73500 Construct Offsite Sidewalk 6 Trash Enclosures 30 Good Construct 8000 40000 Split face black & bollards 40000 40000 Trash Enclosures Uninflated Totals 20000 135000 1891019 1.4258 1.4685 1.5126 Inflation Factor (3%) 1.5580 1.6047 1.6528 Inflated Totals 0 1736019 0 28515 0 1974860

#### **Capital Needs Assessment Materials and Conditions - Architectural**

AGE RUL Cond Action DUR QTY Unit

Replace

15 Good

10 Good 30 Good

25 Good

30 Good 25 Good

25 Good

30 Good

25 Good

25 Good 0 Good



Cost

168 ea

168 ea 7 ls

434 ea

168 ea

84 ea

63 ea

752 sq

172 sq

168 du

3600 If

#### **Capital Needs Assessment Capital Needs Over the Term - Architectural**

**Project: Mullica West Apartments** 

15

10

30

25

30

25

25

30

25

25

Item

Screen and Storm Doors

Exterior Entry Lt Fixtures

Gutters and Downspouts

Mechanical Room Doors

Manufactured Stone Vaneer

Roof (7 bldgs)

Entry Doors

Porch Roof

Demolition

Siding

Windows

	Date:	7/22/2013	Project:	Project: Mullica West Apartments Date: NEW CONSTRUCTION																					
Unit	Total				1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	
Cost	Cost	Comments	Item	H&S	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	Total
200	33600		Screen and Storm Doors		33600	0	0	0	0	0	0	0	0	0	0	0	0	0	0	33600	0	0	0	0	67200
50	8400	Energy Star Rated	Exterior Entry Lt Fixtures		8400	0	0	0	0	0	0	0	0		8400	0	0	0	0	0	0	0	0		16800
45300	317100		Roof (7 bldgs)		317100	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	317100
250	108500		Windows		108500	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	108500
5	18000	515 linear feet per bldg	Gutters and Downspouts	0	18000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	18000
700	117600	Fiberglass Door and Frames	Entry Doors		117600	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	117600
700	58800		Mechanical Room Doors		58800	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	58800
2000	126000		Porch Roof		126000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	126000
275	206800	sq= 100 sq ft	Siding		206800	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	206800
350	60200	sq= 100 sq ft	Manufactured Stone Vaneer		60200	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	60200
500	84000	Apt Interior Demolition	Demolition		84000	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	84000
			Uninflated Totals	0	1139000	0	0	0	0	0	0	0	0	0	8400	0	0	0	0	33600	0	0	0	0	1181000
			Inflation Factor (3%)	1.0000	1.0000	1.0300	1.0609	1.0927	1.1255	1.1593	1.1941	1.2299	1.2668	1.3048	1.3439	1.3842	1.4258	1.4685	1.5126	1.5580	1.6047	1.6528	1.7024	1.7535	
			Inflated Totals	0	1139000	0	0	0	0	0	0	0	0	0	11289	0	0	0	0	52348	0	0	0	0	1202637

## Capital Needs Assessment Materials and Conditions - Mechanical & Electrical



## Capital Needs Assessment Capital Needs Over the Term - Mechanical & Electrical

USDA Rural

Project: Mullica West Apartments

Date: 7/22/2013

Project: Mullica West Apartments

Date: NEW CONSTRUCTION

riojeci.	Widilica VVE	ot Apai tii	iciito							Date.	1/22/2013	1 10,000	munioc	IIICOLA	Jai lillellis							Date		001101	KOCHON	
Item	EUL	AGE	RUL	Cond	Action	DUR	QTY	Unit	Unit Cost	Total Cost	Comments	Item	H&S	1 2014	2 3 2015 2010	4 6 2017	5 6 2018 2019	7 8 2020 2021	9 10 2022 2023	11 12 3 2024 2025	13 14 5 2026 2027	15 16 2028 2029	17 2030		19 20 2032 203	3 Tota
														0	0	C	0	0 0	0	0 0	0 0 0	0	0	0 0	0	0
Switches/ outlets/ athroom exhaust fans/ heater/ shutoff switches	30	0	30	Good	Replace	0	168	Apts	1250	210000		Switches/ outlets/ athroom exhaust fans/ heater/ shutoff switches		210000	0	0 0	0	0 0 0	0	0 0	0 0 0	0	0	0 0	0	0 2100
Light fixtures	30	0	30	Good	Replace	0		Apts	250	42000		Light fixtures		42000	0	0 0	0	0 0 0	0	0 0	0 0 0	0	0	0 0	0	0 420
Smoke detectors	10	0	10	Good	Replace	1		Apts	750	126000	Hardwired	Smoke detectors	0	126000	0	0 0	0	0 0 0	0	126000	0 0 0	0	0	0 0	0 1260	000 3780
Doorbells	30	0	30	Good	Replace	0	168	Apts	130	21840		Doorbells		21840	0	0 0	0	0 0 0	0	0 0	0 0 0	0	0	0 0	0	0 218
Hot Water Heater	20	0	20	Good	Replace	1	168	Apts	1700	285600	Tankless	Hot Water Heater	0	285600	0	0 0	0	0 0 0	0	0 0	0 0 0	0	0	0 0	0 2856	5712
Gas furnace/ A coils/ Condensers	25	0	25	Good	Replace	1	168	Apts	3700	621600		Gas furnace/ A coils/ Condensers	0	621600	0	0 0	0	0 0 0	0	0 0	0 0 0	0	0	0 0	0	0 6216
Main Electric Service	30	0	30	Good	Construct	0		Apts	1500	252000		Main Electric Service		252000	0	0 0	0	0 0 0	0	0 0	0 0 0	0	0	0 0	0	0 2520
Laundry Area Plumbing/Pan	30	0	30	Good	Construct	0	168	Apts	750	126000		Laundry Area Plumbing/Pan		126000	0	0 0	0	0 0 0	0	0 0	0 0 0	0	0	0 0	0	0 1260
-												Uninflated Totals	6 0	1685040	0	0 0	0	0 0 0	0	0 126000	0 0 0	0	0	0 0	0 4116	00 22226
												Inflation Factor (3%	1.0000	1.0000	1.0300 1.06	09 1.0927	1.1255 1.159	3 1.1941 1.2299	1.2668 1.304	48 1.3439 1.384	12 1.4258 1.4685	1.5126 1.558	1.604	7 1.6528	1.7024 1.75	535
												Inflated Totals	3 0	1685040	0	0 0	0	0 0 0	0	0 169333	0 0 0	0	0	0 0	0 7217	43 25761

## Capital Needs Assessment Materials and Conditions - Dwelling Units



## Capital Needs Assessment Capital Needs Over the Term - Dwelling Units

JSDA Rural

Project: Mullica West Apartments

Date: 7/22/2013

Project: Mullica West Apartments

Date: NEW CONSTRUCTION

								Unit	Total			1	2	3	4	5	6	7 8	9	10	11 1	12	13	14 1	15 1	16	17 18	19 20	
Item	EUL	AGE	RUL	Cond	Action	DUR	QTY Unit	Cost	Cost Comments	Item	H&S	2014	2015	2016	2017	2018 2	019 20	2021	2022 2	2023	2024 20	025 2	2026 2	027 20	)28 20	029 2	2030 2031	2032 2033	Total
																													0
Interior Closet Doors	30	0		Good	Replace	0	336 ea	175	58800 6 Panel	Interior Closet Doors		58800	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 0	0 58800
Interior (swing style) Doors	30	0		Good	Replace	0	609 ea	100	60900	Interior (swing style) Doors		60900	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 0	0 60900
2nd floor mech. room doors	30	0		Good	Replace	0	84 ea	600	50400 Flush Door	2nd floor mech. room doors		50400	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 (	0 50400
Misc Framing/ Drywall	40	0	40	Good	Replace	0	168 Apt	1000	168000	Misc Framing/ Drywall		168000	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 (	0 168000
Handicapped Modifications: Framing, Rough plumbing										Handicapped Modifications: Framing, Rough plumbing and																		1	
and Electric	25	0		Good	Construct	1	9 ea	26250	236250	Electric		236250	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 (	0 236250
Refrigerators	15	0		Good	Replace	1	168 ea	700	117600	Refrigerators		117600	0	0	0	0	0	0	0 0	0	0	0	0	0	11	7600	0 0	0 (	0 235200
Cabinets & Countertops	30	0		Good	Replace	1	168 ea	3500	588000	Cabinets & Countertops		588000	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 (	0 588000
Fire Extinguishers	7	0	7	Good '	Replace	0	168 Apts	45	7560	Fire Extinguishers	0	7560	0	0	0	0	0	0 756	0 0	0	0	0	0	0	0	7560	0 0	0 (	0 22680
Tile	15	0	15	Good	Replace	1	168 ea	700	117600	Tile		117600	0	0	0	0	0	0	0 0	0	0	0	0	0	11	7600	0 0	0 (	0 235200
Range	15	0	15	Good	Replace	1	168 ea	550	92400	Range		92400	0	0	0	0	0	0	0 0	0	0	0	0	0	0 9	92400	0 0	0 (	0 184800
Range Hood	15	0	15	Good	Replace	1	168 ea	110	18480	Range Hood		18480	0	0	0	0	0	0	0 0	0	0	0	0	0	1	8460	0 0	0 (	0 36940
Vanity Top	20	0	20	Good	Replace	1	168 ea	325	54600	Vanity Top		54600	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 (	0 54600
Tub surround	20	0	20	Good	Replace	1	168 ea	400	67200	Tub surround		67200	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 (	0 67200
Faucets/drains/misc fittings	20	0	20	Good	Replace	1	168 Apt	500	84000 Includes Shut Off Valves	Faucets/drains/misc fittings	0	84000	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 84000	0 168000
LVT/ sheet vinyl/ ceramic tile	15	0	15	Good	Maintain	1	98728 sf	4	394912	LVT/ sheet vinyl/ ceramic tile	0	394912	0	0	0	0	0	0	0 0	0	0	0	0	0 39	4912	0	0 0	0 (	0 789824
Carpet	7	0	7	Good	Replace	0	4889 sq yd	14	68446 Carpet in bedrooms only	Carpet	0	68446	0	0	0	0	0	0 6844	6 0	0	0	0	0	0	0 6	88446	0 0	0 (	0 205338
Paint	8	0	) 8	Good	Maintain	0	168 Apt	3250	546000 Low VOC	Paint		546000							54600							5	54600	1	655200
Expand 2BR to 3BR	50	0	50	Good	Construct	0	42 ea	22500	945000	Expand 2BR to 3BR		945000	0	0	0	0	0	0	0 0	0	0	0	0	0	0	0	0 0	0 (	0 945000
										Uninflated Totals	0	3676148	0	0	0	0	0	0 7600	54600	0	0	0	0	0 39	4912 42	22066 5	54600 0	0 84000	0 4762332
										Inflation Factor (3%)	1.0000	1.0000	1.0300	1.0609	1.0927	1.1255	1.1593 1	.1941 1.229	9 1.2668	1.3048	1.3439 1	1.3842	1.4258	1.4685	1.5126	1.5580	1.6047 1.6528	1.7024 1.7535	5
										Inflated Totals	0	3676148	0	0	0	0	0	0 9347	8 69166	0	0	0	0	0 59	7340 65	57565	87617 0	0 147295	5 5328608



### **AFFORDABLE SALEM, INC.**

P.O. Box 1, Titusville, NJ 08560 609-730-8138 • 609-730-8139

March 20, 2014

Susanne H. Rhudy Land Use Administrator/Joint Land Use Board Secretary Municipal Housing Liaison Township of Harrison 114 Bridgeton Pike Mullica Hill, NJ 08062

Re: Block 52, Lot 9, 5.27 Acres, 54 Woodstown Road, Mullica Hill, NJ 08062

Dear Ms. Rhudy:

I am writing to you as the contract purchaser of the 54 Woodstown Road and, through a separate business (Rukenstein & Associates, LLC), the Developer of Mullica West Apartments. This correspondence is a summary of our site inspection of 54 Woodstown Road as part of our due diligence for both properties which raised the following conditions:

1. Dilapidated and obsolete buildings – There exists both a shed and garage that are clearly in disrepair and unsafe. These structures are of insufficient size for today's standards and based on condition and obsolescence would be best suited for demolition.





2. Unsafe and Unsanitary Conditions - The single family home on this property maintains substandard and unsanitary conditions. There are several areas where water leaks remain evident on the ceilings. Further the foundation and mortar joints are in disrepair. Taken together with the dilapidated structures identified above, the property is conducive to unwholesome living conditions.



Based on our review both properties require substantial rehabilitation to be brought up to a standard that is expected for usability and that based on our analysis this works is beyond the market for financial feasibility.

We believe that developing these properties as part of an overall redevelopment plan will provide the opportunity to fully utilize both properties to the benefit of the community and improve circulation for the residents of Mullica West by creating direct access to Woodstown Road and the nearby shopping centers along Route 77 that are within a half mile walking distance.

Thank you for the opportunity to submit this information.

Sincerely,

Ron Rukenstein, PP, AICP